

Photo Schedule

of

35 Queens Grove
London
NW8

September 2010

Cluttons LLP is a limited liability partnership in England and Wales under the number OC310771, registered office and head office - Portman House, 2 Portman Street, London W1H 6DU.

Regulated by RICS.



INVESTOR IN PEOPLE

Cluttons - in the United Kingdom, Europe, Middle East, South Africa and the Caribbean.



Photo 1 – Front Elevation




Photo 2 – Front Elevation




Photo 3 - Front Elevation




Photo 4 – Two storey side addition



Photo 5 – Side Elevation (Front)




Photo 6 – Side Elevation (Rear)




Photo 7 – Rear Elevation




Photo 8 – Rear Elevation of side addition




Photo 9 – Rear Elevation, balcony and stairs



Photo 10 – Rear Elevation basement level



Photo 11 – Rear garden




Photo 12 – Japanese Knotweed




Photo 13 – Stairs leading to basement




Photo 14 – Basement, proposed 'Family Area'




Photo 15 – Basement, proposed kitchen



Photo 16 – Basement, proposed utility room




Photo 17 – Basement, existing bathroom




Photo 18 – Basement, proposed cloakroom




Photo 19 – Ground Floor, doors to be retained



Photo 20 – Ground Floor, cornicing



Photo 21 – Ground Floor, existing kitchen




Photo 22 – Ground Floor, front reception room



Photo 23 - Ground Floor, proposed front and rear reception rooms




Photo 24 – Ground Floor, cloakroom




Photo 25 – First Floor, master bedroom



Photo 26 - First Floor, rear bedroom



Photo 27 – First Floor, bathroom




Photo 28 – First Floor, bathroom




Photo 29– First Floor landing




Photo 30 – Underside of 2nd Floor landing




Photo 31 – Second Floor, landing




Photo 32 – Second Floor, en-suite




Photo 33 – Second Floor, en-suite




Photo 34 – Second Floor, bedroom (Front)




Photo 35 – Second Floor, bedroom (Rear)




Photo 36 – Second Floor, bedroom,
vertical cracking in corner