MAX026

## Comment on Sound from Original Acoustic Statement

All the existing units were operational. The units have fans that cut in and out on demand. Not all the fans were operating throughout the measurements as the demand changed. This is normal for such units. We were told that the demand on the day of the measurements was typical. We, therefore, believe that the noise we measured from the existing units was typical. Of course, the fact that not all the fans on the existing units were operating all the time is a worst case as far as assessing the new units is concerned. Our brief was to determine the impact of the new units, not to assess the impact of the existing units. That said, the main noise in the area was from building services units on other buildings, not the Maverick units.

----- Forwarded by Richard Clough/Mid/Aes on 24/01/2008 12:07 -----

"Miller, Hugh" <Hugh.Mille <u>r@camden.go</u> v.uk>

24/01/2008 11:50 To <<u>richard.clough@aes-labs.co.uk</u>> cc Subject

FW: Acoustic noise report for 40 Churchway, London (Your ref: 14603)