

Solid timber hoarding to east and south elevations

Site rubble

Site rubble

Existing storage shed

Steel containers left on site

Concrete ground slab of former c/c building with trenches cut through

Wire mesh fencing to north west elevation

Contractor's Site Access Road

