



Photograph 49 – Roof hatch



Photograph 50 – Blown plasterwork and crack running to left of window opening




Photograph 51 – Hairline crack running vertically down eastern wall




Photograph 52 – Separation between exposed ceiling partition walls


SECOND FLOOR – ROOM 1



Photograph 53 – Separation between partition walls, solid walls and ceiling



Photograph 54 – Separation between partition walls and solid wall



Photograph 55 – Glazing repair top left pane over door opening




Photograph 56 – Door latch-keep damaged

SECOND FLOOR – ROOM 2



Photograph 57 – General



Photograph 58 – General



Photograph 59 – General




Photograph 60 – Blown plasterwork to chimney breast




Photograph 61 – Blown plasterwork to chimney breast




Photograph 62 – Displaced double socket to left of chimney breast




Photograph 63 – Hairline stress crack running down right hand side face of breast



Photograph 64 – Broken window pane to bottom sash of right hand window



Photograph 65 – Scraps to outside face of door




Photograph 66 – Trunking Unit




Photograph 67 – Crack running down north western corner


SECOND FLOOR - LOBBY



Photograph 68 – Raking crack over door to lobby on both sides



Photograph 69 – Separation above partition walls



Photograph 70 – Stains to carpet




Photograph 71 – Stains to carpet

SECOND FLOOR - ROOM 3




Photograph 72 – General




Photograph 73 – Damp staining and damaged decorations in north eastern corner to wall and ceiling




Photograph 74 – Cracked plaster to left of heater and missing socket in skirting



Photograph 75 – Displaced socket below window




Photograph 76 – Hole in partition wall within south eastern corner



Photograph 77 – Scraps and scuffs to door

SECOND FLOOR - ROOM 4



Photograph 78 – Pendant light fitting face plate within ceiling