



Photograph 261 – Front elevation – Hairline crack to rendered band



Photograph 262 – 3rd Floor level detail




Photograph 263 – Cast iron plate not flush to wall




Photograph 264 – Front light well




Photograph 265 – Metal stairs down to light well



Photograph 266 – Corrosion to underside of metal steps



Photograph 267 – Light well



Photograph 268 – Timber decay to base of timber door to under pavement vault