

- 1

EXISTING CASEMENT WINDOWS CHANGED TO SASH WINDOW WITH PAINTED DOUBLE GLAZED TIMBER FRAMES
- 2

EXISTING YELLOW STOCK BRICK WALL RETAINED. BRICK TO BE CLEANED
- 3

NEW BLACK PAINTED, GALVANISED METAL ACCESS & ESCAPE LADDER TO REPLACE PART OF EXISTING CONCRETE STEPS.
- 4

NEW 50mm x 25mm HORIZONTAL SELF FINISHED WESTERN RED CEDAR CLADDING FIXED TO TREATED SOFT WOOD BATTENS
- 5

NEW PAINTED ALUMINIUM DOUBLE GLAZED DOOR & FIXED SIDE LIGHTS
- 6

NEW WALL FINISHED IN YELLOW STOCK BRICKS TO MATCH EXISTING
- 7

NEW ROOF, FASCIA RAIN WATER GOODS FINISH IN PRE WEATHERED BLUE GREY ZINC, LEAD COLOUR.
- 8

NEW 50mm x 25mm HORIZONTAL SELF FINISHED WESTERN RED CEDAR CLADDING FIXED TO TREATED SOFT WOOD BATTENS, ON WALL BEHIND METAL LADDER
- 9

EXISTING WINDOW TO GARDEN FLAT
- 10

EXISTING PAINTED RENDERED WALL, MADE GOOD & REDECORATED, ABOVE NEW MIRROR
- 11

NEW PAINTED ALUMINIUM DOUBLE GLAZED DOOR
- 12

NEW ANTHRACITE COLOUR BRICK PAVING LAID TO FALLS TO BACK INLET GULLY
- 13

EXISTING SOIL & VENT PIPES & RAIN WATER PIPES TO BE REDIRECTED TO NEW INSPECTION CHAMBER/MAN HOLE. ALL PIPEWORK LAID TO FALLS. ALL REDIRECTED DRAINAGE TO BE PROVIDED WITH RODDING ACCESS PANELS. NEW PIPE WORK IN BLACK PAINTED, CAST IRON FINISH TO MATCH EXISTING
- 14

NEW PAINTED ALUMINIUM DOUBLE GLAZED WINDOW TO SHOWER ROOM IN OBSCURE GLASS
- 15

NEW MIRROR WITH SAFETY GLASS FIXED OVER EXISTING RENDERED WALL. HEIGHT SAME AS HEAD OF NEW DOOR FRAMES
- 16

EXISTING CONCRETE STEPS TO BE RETAINED TO THREE RISERS AND NEW LANDING PROVIDED
- 17

NEW TIMBER GATE FINISH IN WESTERN RED CEDAR WITH TREATED TIMBER POSTS AND GALVANISED IRONMONGERY WITH SELF CLOSERS
- 18

EXISTING RAIN WATER PIPEWORK REDIRECTED INTO NEW GUTTER, FINISH TO MATCH EXISTING