

DESCRIPTION OF PHOTOGRAPHS

Photo 1 : View of upper terrace from lower terrace

Photo 2 : View of Master Bedroom windows

Photo 3: View of window to be replaced by new means of escape door

Photo 4: View across lower terrace showing existing means of escape circular staircase

Photo 4 : View of upper terrace showing site for new means of escape staircase

Photo 5 : View of upper terrace showing site for new means of escape staircase

Photo 6 : View from Library area onto staircase obstructing amenity area of terrace