



Photograph 16. Back of front door. Much good original detailing but obtrusive services.



Photograph 17. Looking through the hallway from the front; there is no light at the end of the hall or from the landing due to the modern interventions.






*Photograph 18. Ground Floor. Original door in wrong location (to be resited to hallway). Interconnecting rooms recently blocked up.*



*Photograph 19. Ground Floor. Typical of office installations throughout the house.*





Photograph 20. Ground Floor Front. Crude plaster casts added "recently" to the ceiling, to be removed.



Photograph 21. Original cornice behind crude over-cornice. Also note blocking up of wide doorway and "alien" panel above the door.





Photograph 22. Ground Floor Rear. Original fireplace with altered hearth (original is underneath). (The original fireplaces survives in damaged state to front room). Also note original dado rail and skirting.



Photograph 23. First Floor Room (Rear). Fireplace removed and blocked – to be reinstated (original was marble to match (damaged) fireplace in front room; proposed to be instated to original design.