




Photograph 24. Second Floor Front – original fireplace.



Photograph 25. Second Floor Front. Original cornice obscured by recent partition.



Photograph 26. Second Floor Front. Second fireplace hearth in the room. Very unusual feature.



Photograph 27. Original detailing above the hearth referred to above.



Photograph 28. Third Floor. Office fitting out typical of this floor.



Photograph 29. Third Floor. Office fit-out; but early hearth still in place to be retained.



Photograph 30. Front step. (Defective and leaking).



Photograph 31. Basement window into small rear gridded area. Proposed to be glazed double doors using mouldings to match.
NB: This window has been a doorway in the past at some stage.



Photographs 32 and 33. Views into rear garden No. 56 Doughty Street.



Photograph 33.