


Ref:	Location	Defect	Quantity	Repair Details
01.	West Elevation North Abutment	Open Joints	30m²	Rake out and repoint in accordance with Drawing NR/CIV/SD/101
02.	West Elevation North Abutment	Vegetation Growth	1.5m²	Treat Vegetation with Glyphosate and allow to die off, resulting debris to be removed from site. Resulting open joints to be raked out and repointed in accordance with Drawing NR/CIV/SD/101.
03.	West Elevation North Abutment	Tree Growth	1No.	Treat Vegetation with Glyphosate and allow to die off, resulting debris to be removed from site.
04.	West Elevation North Abutment	Fractured Brickwork	1m	Stitch fracture in accordance with NR/CIV/SD/109
05.	East Elevation South Abutment	Open Joints	4m²	Rake out and repoint in accordance with Drawing NR/CIV/SD/101
06.	East Elevation North Abutment	Open Joints	30m²	Rake out and repoint in accordance with Drawing NR/CIV/SD/101
07.	East Elevation North Abutment	Vegetation Growth	1,5m²	Treat Vegetation with Glyphosate and allow to die off, resulting debris to be removed from site. Resulting open joints to be raked out and repointed in accordance with Drawing NR/CIV/SD/101.
08.	North Abutment	Fractured Brickwork	4m	Stitch Fracture in accordance with Drawing NR/CIV/SD/109
09.	North Abutment	Fractured Brickwork	0.7m	Stitch Fracture in accordance with Drawing NR/CIV/SD/109

- ALL DIMENSIONS ARE IN MILLIMETRES UNLESS STATED OTHERWISE. DO NOT SCALE FROM THIS DRAWING. THIS DRAWING IS BASED ON AVAILABLE NETWORK RAIL RECORD INFORMATION AND A TOPOGRAPHICAL SURVEY UNDERTAKEN BY BRIDGEWAYS LTD. ON 05/08/2013. ALL BRICKWORK REPAIRS ARE TO BE CARRIED OUT IN ACCORDANCE WITH THE FOLLOWING DRAWINGS AND THE SPECIFICATIONS INCLUDED THEREON:-
- DETAILED AS BUILT RECORDS IN THE FORM OF BEFORE AND AFTER PHOTOGRAPHS OF EACH REPAIR ARE TO BE PROVIDED.
- ALL REPAIR LOCATIONS ARE TO BE MARKED OUT BY THE CONTRACTOR AND AGREED WITH THE ENGINEER / CLIENT'S REPRESENTATIVE.
- NO ADDITIONAL WORKS TO BE UNDERTAKEN WITHOUT PRIOR WRITTEN AUTHORISATION FROM NETWORK RAIL.
- ALL VEGETATION ON AND WITHIN 3m OF THE STRUCTURE TO BE TREATED WITH GLYPHOSATE OR SIMILAR APPROVED HERBICIDE AND ALLOWED TO DIE. ALL RESULTING DEBRIS TO BE CUT BACK AND REMOVED FROM SITE. ROOT SYSTEMS ARE TO BE FULLY REMOVED AND ANY DAMAGED STRUCTURAL ELEMENTS REMAINING AS PART OF THE FINAL DESIGN MADE GOOD.



- 1. ILLNESS DUE TO USE OF CHEMICAL HERBICIDE OR CEMENTITIOUS PRODUCTS.

  2. INJURY DUE TO DISPLACING LOOSE BRICKWORK.
- 3. INJURY THROUGH DAMAGING SERVICES.



_					
2	17/01/14	REVISED SCOPE OF WORKS	КН	RJ	RES
1	27/09/13	FIRST ISSUE	RD	RJ	RES
•	Date	Description of Revisions	Drawn	Chkd	Appr
us	E.C	01 APPROVAL IN PRI	NCIDI	=	

A02	17/01/14	REVISED SCOPE OF WORK
A01	27/09/13	FIRST ISSUE
Rev	Date	Description of Revisions
Status	, E-0	001 APPROVAL IN
Desig	ners	
	structure	Projects
	ls Design (	
Man	chester	
Man	re One	
Man Squa 4 Tra		

JRT2/5 CHURCH HILL ROAD FOOTBRIDGE

## BRICKWORK REPAIRS

Designer	R. JAKEMAN	Signed	Leren	22 /1/	
Drawn	R. DIVILLY	Signed A	illes!	7 Date 22/1/Y	
Checked	R. E. STANDRING	Signed		4 22/1/	
Approved	R. E. STANDRING	Signed	Je.	Date 2.2 / / /	
Scale(s) at	A1 Sheet Size A1 594 x 841	ELR & Mileage		1	
AS SHO	WN	ELR: JRT2	2m 0	593yds	
Atternative	Reference		Sheet	Sheets	

LNE/129588/ECV/DRG/IAB/103

A02