

© COPYRIGHT Mace Group
NOT TO BE REPRODUCED WITHOUT WRITTEN PERMISSION. · BECAUSE OF POSSIBLE SCALING ERRORS IN ELECTRONIC AND HARDCOPY REPRODUCTION DO NOT SCALE FOR CONSTRUCTION PURPOSES. · ALL DIMENSIONS TO BE CHECKED & VERIFIED ON SITE PRIOR TO CONSTRUCTION. Safety, Health and Environment Information The signifigant unusual hazards / risks associated with this type of work are noted as: CONSTRUCTION OPERATION AND MAINTENANCE DISMANTLING/DEMOLITION NOTE - TO BE READ IN CONJUNCTION WITH RISK REGISTER EXISTING LEAD RECTANGULAR RAIN WATER PIPE AND EXISTING LEADED LIGHT WINDOW EXISTING METAL FRAMED MULTI-PANE WINDOW EXISTING PORTLAND STONE FACADE EXISTING STONE BALCONIES WITH METAL RAILINGS EXISTING WHITE GLAZED FACING BRICK PROPOSED GLAZED ROOF PROPOSED GLAZED PERIMETER FLAT ROOF PROPOSED STRUCTURAL CONCRETE COLUMNS PROPOSED DECK AND GALLERY STRUCTURE PROPOSED GLAZED BALUSTRADE WITH BRONZE PROPOSED NEW OPENINGS 25.04.14 RAINWATER HARVESTING TANKROOM ADDED STAGE 3 University of London 155 Moorgate, London, EC2M 6XB www.macegroup.com SOAS INTO SENATE HOUSE MALET STREET LONDON, WC1E 7HU PROPOSED SECTION 2 DATE APRIL 2013

PROJECT CODE | DISC. | VIEW TYPE | VIEW CAT. | LEVEL | DWG. NO. | SOAS - A - SEC - GEN - XX - 372

1 of 1 1:100 @ A1 P 4 INFORMATION HANDLING CLASSIFICATION UNRESTRICTED

C:\BIM\MAC_STAGE3_PLANNING_RESUBMISSION_lisa.torje.rvt