


General notes.

1. This drawing to be read in conjunction with all relevant Architects and Engineers drawings and specifications.
2. 1,2,3 etc indicates "hit and miss" sequence of underpinning.
3. Concrete grade RC40
4. For suggested construction sequence refer to drawing 03

| Rev. | Date | By |
|------|------|----|
|------|------|----|



Trevor Scott
Consulting Structural Engineer

Trevor Scott Consulting Ltd., 8 Herons Mead, Bramham, Bedford, MK43 8LQ
Telephone 01234 822153 email scott.gt@gmail.com
Company Reg. No. 8396786

13/15 John's Mews, WC1N 2PA

Drawn by
GTS

Commenced
Feb'14

Scale at A1
1:50

BASEMENT GA

1420

02

\$FILE\$
\$MODEL\$

Plotted on \$DATE\$

Time \$TIMES\$