

© COPYRIGHT Mace Group

NOT TO BE REPRODUCED WITHOUT WRITTEN PERMISSION.

BECAUSE OF POSSIBLE SCALING ERRORS IN ELECTRONIC AND HARDCOPY REPRODUCTION DO NOT SCALE FOR CONSTRUCTION PURPOSES. · ALL DIMENSIONS TO BE CHECKED & VERIFIED ON SITE PRIOR TO CONSTRUCTION.

Safety, Health and Environment Information

The signifigant unusual hazards / risks associated with this type of work are noted as:

CONSTRUCTION

CI CDM 27 REFURBISHMENT OF EXISTING FACADE

OPERATION AND MAINTENANCE

OI CDM 28 ACCESS FOR CLEANING & MAINTENANCE

DISMANTLING/DEMOLITION

NONE

NOTE - TO BE READ IN CONJUNCTION WITH RISK REGISTER

EXISTING LEAD RECTANGULAR RAIN WATER PIPE AND

EXISTING STONE BALCONIES WITH METAL RAILINGS

02 EXISTING LEADED LIGHT WINDOW

EXISTING METAL FRAMED MULTI-PANE WINDOW EXISTING PORTLAND STONE FACADE

STONE CILL

EXISTING WHITE GLAZED FACING BRICK

PROPOSED GLAZED ROOF

PROPOSED GLAZED PERIMETER FLAT ROOF

PROPOSED STRUCTURAL CONCRETE COLUMNS PROPOSED DECK AND GALLERY STRUCTURE

PROPOSED GLAZED BALUSTRADE WITH BRONZE

PROPOSED NEW OPENINGS

14 EXISTING OPENINGS

FOR REPAIRS & REMEDIAL WORK TO ALL EXTERNAL DOORS, WINDOWS, FACADE, RAINWATER GOODS AND STONE FATURES REFER TO DRAWINGS AND SPECIFICATIONS BY DONALD INSOLL

21.08.14 ACOUSTIC PANELS ADDED TO EAST COURTYARD LOWER GROUND. EXISTING DOOR RETAINED.

25.11.13 TENDER ADDENDUM 2 11.11.13 TENDER ADDENDUM 16.09.13 TENDER

PROJECT STATUS

INFORMATION





SOAS INTO SENATE HOUSE MALET STREET LONDON, WC1E 7HU

PROPOSED EAST & WEST **COURTYARD ELEVATIONS**

@ A1 T 4 1 of 1 1:100

UNRESTRICTED