

· BECAUSE OF POSSIBLE SCALING ERRORS IN ELECTRONIC AND HARDCOPY REPRODUCTION DO NOT SCALE FOR CONSTRUCTION PURPOSES.

The signifigant unusual hazards / risks associated with this type of work are

DEMOLITION OF EXISTING STRUCTURE

OPERATION AND MAINTENANCE


DISMANTLING/DEMOLITION


(000) REFER TO PHOTOGRAPHIC DEMOLITION SURVEY 28731-SOAS-A-REP-XXX-XX-004

PHOTOGRAPHIC DOOR SURVEY 28731-SOAS-A-REP-XXX-XX-003 AND SCHEDULE FOR REUSE AND RECYCLING OF DOORS 28731-SOAS-A-SHL-

ALL NEW WALL OPENINGS SHOWN ARE ARE TO BE 2100 HIGH UNLESS OTHERWISE STATED. SETTING OUT DIMENSIONS FOR WALL OPENINGS AND SLAB OPENINGS ARE TO BE CONFIRMED SUBJECT TO

REVISON NOTE C2: DOOR 133B AND E116 HAS NOT DOOR **REVISION NOTE C1: DEMOLITION RELATED TO PLANNING** CONDITION 7 HAS MOVED TO SHEET 193. A NUMBER OF WALL TILES IN THE TOILETS TO BE SALVAGED AND REUSED TO REPLACE TILES ON WINDOW CILLS IN TOILETS. WALL AND DOOR EM02 ON MEZZANINE TO BE DEMOLISHED. ELECTRICAL CUPBOARD TO BE









SOAS INTO SENATE HOUSE

FIRST & GROUND FLOOR MEZZANINE

DATE 21.08.14

@ A1 C 2