

© COPYRIGHT Mace Group
NOT TO BE REPRODUCED WITHOUT WRITTEN PERMISSION.

 BECAUSE OF POSSIBLE SCALING ERRORS IN ELECTRONIC AND HARDCOPY REPRODUCTION DO NOT SCALE FOR CONSTRUCTION PURPOSES. · ALL DIMENSIONS TO BE CHECKED & VERIFIED ON SITE PRIOR TO CONSTRUCTION.

Safety, Health and Environment Information

The signifigant unusual hazards / risks associated with this type of work are noted as:

> CONSTRUCTION DEMOLITION OF EXISTING STRUCTURE

> > DISMANTLING/DEMOLITION

NOTE - TO BE READ IN CONJUNCTION WITH RISK REGISTER

OPERATION AND MAINTENANCE

DEMOLITION

DOOR FRAME AND ARCHITRAVE TO BE REMOVED

= WALLS TO BE REMOVED

SLAB OPENING TO BE CREATED

(000) REFER TO PHOTOGRAPHIC DEMOLITION SURVEY 28731-SOAS-A-REP-XXX-XX-004 E101 DOOR TAGS WITH THE PREFIX E REFER TO

PHOTOGRAPHIC DOOR SURVEY 28731-SOAS-A-REP-XXX-XX-003 AND SCHEDULE FOR REUSE AND RECYCLING OF DOORS 28731-SOAS-A-SHL-GEN-XX-917

GENERAL NOTE: ALL NEW WALL OPENINGS SHOWN ARE ARE TO BE 2100 HIGH UNLESS OTHERWISE STATED. SETTING OUT DIMENSIONS FOR WALL OPENINGS AND SLAB OPENINGS ARE TO BE CONFIRMED SUBJECT TO SUBCONTRACTOR REQUIREMENTS.

REVISION NOTE C2: DOOR 218B HAS NO EXISTING DOOR

REVISION NOTE C1:DEMOLITION RELATED TO PLANNING CONDITION 7 HAS MOVED TO SHEET 194. WALL AND DOOR E208 GRIDLINE 1C TO BE DEMOLISHED.

21.08.14 CONSTRUCTION 01.08.14 CONSTRUCTION

University of London

CONSTRUCTION

mace

155 Moorgate, London, EC2M 6XB www.macegroup.com

SOAS INTO SENATE HOUSE MALET STREET LONDON, WC1E 7HU

DEMOLITION SECOND FLOOR PLAN

DRAWN BY JU DATE 21.08.14

SOAS - A - PLN - DEM - 02 - 214

@ A1 C 2 1 of 1 1:100

UNRESTRICTED