


Photo 01
Existing Roof
Eternit Slates and Felt To Dormers

Photo 02 & 03 Proposed roof, natural slates with Lead Dromers



MISCELLANOUS PHOTOS



Photo 04 Stairs to Lower Ground Floor

Woodworm at upper level and damp rot at lower level Replace with new, pine staircase to match, Retain handrail. New square spindles




Photo 05
First Floor Drawing Room, F02
Showing existing Concrete beam under windows
Concrete infill in between windows
Joists extended and bolted to existing



Photo 06 Landing G04 Rotten floor joists. (Woodworm) To be replaced



Photo 07 Master Bedroom S01 Photo showing new floor joists bolted to Origional



Photo 08
Existing Rear Elevation
Some non Origional Windows, poor brickwork and Pointing





Photos 09 and 10 New Lime Mortar pointing Bricks replaced with second hand bricks to match Downpipes replaced with cast Iron

MISCELLANOUS PHOTOS




Photo 11 Front Elevation

Supply and install new GRG high level Cornice, to match neighbours To further detail Downpipes replaced with cast Iron



Photo 12 Third Floor, Rear Room T03 Showing new steels to take up sag in roof. Ex celing joists and roof rafters retained