Application No:	Consultees Name:	Consultees Addr:	Received:	Comment:	Response:	Printed on:	30/12/2014	09:05:20
2014/7593/P	Sandra Crisp	Flat 9 11 Dennington Park Road	17/12/2014 12:49:52	COMMNT	windows in the main room are in a poor state of repair and badly leak retain heat, resulting in high fuel bills and very bad condensation. Ther taking up about a third of the front-facade to compound the problem.  The kitchen, built atop a narrow a roof, has leaky windows panes all a therefore particularly cold as there is also no proper external wall, just	I live at the stated dwelling and totally support the planning application. The current old, wooden sash windows in the main room are in a poor state of repair and badly leak heat - Making it very difficult to retain heat, resulting in high fuel bills and very bad condensation. There are 2 large full-length window taking up about a third of the front-facade to compound the problem.  The kitchen, built atop a narrow a roof, has leaky windows panes all along one side. The kitchen is therefore particularly cold as there is also no proper external wall, just a sandwich of thin hardboard. If the winter, the temperature is roughly the same as outside and very cold, there is no space for heating.		