

## Drawing 005 - Existing Window:

Could not obtain access to the rear of the property, therefore no onsite photo was taken.

## Drawing 005

This sash window is on the rear elevation, and is on the fourth floor of the property.

