



2013/2481/P

Information relating to the discharge of condition 2(a) – External Materials and finishes



1

2




5


6




7



4




8



9



10



3


SAMPLE KEY:

1. Metalwork: windows/entrance/pergola uprights
2. Metalwork: mesh to north elevation windows.
3. Metalwork: stainless steel pergola canopies
4. Metalwork: mesh to entrance portal
5. Brick: example 'buff' brick
6. Brick: example 'white' brick
7. Precast: roof coping
8. Render: balconies
9. Render: west flank wall
10. Render: carpark/service area - north elevation

Building T5 SK_P8

Submitted samples sheet

To be read in conjunction with sample product info - SK_1-5




North and south elevation - Buff mix




Courtyard, balcony and 02-07 north elevation - White mix


Building T5
SK_P1
Condition 2 (a)
Brickwork - As viewed on site 14.01.15



*Metalwork: Entrance, window frames, pergola uprights.
Powder coated aluminium/steel - Interpon - Gris: 2500 Sable: Futura*




*Metalwork: Framed mesh, north elevation.
Powder coated aluminium/steel - Metallic RAL: 9006*



*Metalwork: Perforated entrance soffit/bike storage door
Aluminium - no finish*

Building T5
SK_P2
Condition 2 (a)
General Metalwork
 - As viewed on site 14.01.15




*Render: Balcony Soffits
Sto - Fine 1mm aggregate - Colour ref 31436*




*Render: West,elevation
Rockwool topcoat - 1.5mm aggregate - Colour ref 8C46*

**Building T5
SK_P3
Condition 2 (a)
Render. Balcony and west elevation**



*Metalwork: North Elvation , Ground Floor.
Powder coated aluminium louvre, doors, rainscren cladding - RAL 7022*



*Metalwork:: North Elevation, Car Park.
Rockwool Top Coat - 1.5mm aggregate - 2022*

Building T5
SK_P4
Condition 2 (a)
Render + Metalwork. Northe elevtion 'Service Area'.