



- Existing scaffold pole balustrade to be replaced with frameless glass balustrade
 Remove vine and root taking care not to disturb existing building fabric
 Brickwork pointing generally to be repaired.
 Underpin bay to engineer's design. Repair brickwork to match existing.
 Replace all windows with new timber double glazed copies of originals. All to be weighted box sash type with bars and mouldings exactly matching existing.
 In-line slate vents to SVP and bathroom extractor. Matching colour to existing slates.

EXISTING PROPOSED

NOTES

Architecture for London Limited

This drawing is copyright. All rights reserved. Do not scale from this drawing: work from figured dimensions only.



82 Clerkenwell Road, London, EC1M 5RF e: mail@architectureforlondon.co.uk



t: 020 7127 0696

w: www.architectureforlondon.com

PROJECT TITLE 25 DARTMOUTH PARK HILL DRAWING TITLE EX & PR FRONT ELEVATION

DWG STATUS PLANNING

| DRAWN | BR | FILE | xxx | DATE | 01-07 | '-14 | REVISION | |
|---------|----|---------|------|-------|-------|------|----------|--------|
| CHECKED | TD | JOB NO. | 1442 | SCALE | 1:100 | @ A3 | DWG NO. | GA 111 |