

Heritage Statement Incorporating Photographic Images for repair works to the wall at Holly Terrace, N6 6LX.

The wall was constructed circa early 19th Century and comprises of a brick built wall with stone coping stones. The wall is situated on the boundary of Holly Terrace and the grounds of 1 Holly Terrace which are grade II listed. The wall comprises lime based mortar, stone capping and cement render to low level.

The proposed wall repairs are straightforward and consist of roof alterations are straightforward and consist of repointing with a lime based mortar, replacing missing and defective bricks, as well as removing vegetation and replacing existing render. The purpose of the repairs is to improve the stability of the wall, therefore ensuring the safety of the residents when walking through Holly Terrace and within the grounds of 1 Holly Terrace.

The coping stones will be retained as well as the vast majority of the existing brick work. The wall will be cleaned to remove dirt and improve the look.

The proposed repairs will be in keeping with the character and appearance of the existing wall.

The image below shows the existing wall (viewed from the grounds of 1 Holly Terrace).

