



General notes.

1. This drawing to be read in conjunction with all relevant Architects and Engineers drawings and specifications.
2. 1,2,3 etc indicates "hit and miss" sequence of underpinning.
3. Concrete grade RC40
4. For suggested construction sequence refer to drawing 03

2. 1,2,3 etc indicotes "hit and miss" sequence of underpinning.

- ### 3. Concrete grade RC40

4. For suggested construction sequence refer to drawing 03

Rev.	Date	By	
A	Sept'14	GTS	Bosement piled following recommendations from site investigation report.

Trevor Scott
Consulting Structural Engineer

Ivor Scott Consulting Ltd., 8 Herons Wood, Brennan, Bedford, MK43 8LQ
Telephone 01234 822153 email scott.ig@gmail.com
Company Reg. No. 8396786

13/15 John's Mews, WC1N 2PA

Drawn by
GTS

Commenced
Feb'14Scale at Al
1:50

BASEMENT GA

Job No.
1420

02A

Plotted on **\$DATES\$**Time **8 TIMES**