

© COPYRIGHT Mace Group

NOT TO BE REPRODUCED WITHOUT WRITTEN PERMISSION. BECAUSE OF POSSIBLE SCALING ERRORS IN ELECTRONIC AND HARDCOPY REPRODUCTION DO NOT SCALE FOR CONSTRUCTION PURPOSES. · ALL DIMENSIONS TO BE CHECKED & VERIFIED ON SITE PRIOR TO CONSTRUCTION. Safety, Health and Environment Information The signifigant unusual hazards / risks associated with this type of work are noted as: CONSTRUCTION CI CDM 27 REFURBISHMENT OF EXISTING FACADE OPERATION AND MAINTENANCE OI CDM 28 ACCESS FOR CLEANING & MAINTENANCE DISMANTLING/DEMOLITION NONE NOTE - TO BE READ IN CONJUNCTION WITH RISK REGISTER EXISTING LEAD RECTANGULAR RAIN WATER PIPE AND HOPPERS EXISTING LEADED LIGHT WINDOW EXISTING METAL FRAMED MULTI-PANE WINDOW EXISTING PORTLAND STONE FACADE EXISTING STONE BALCONIES WITH METAL RAILINGS EXISTING WHITE GLAZED FACING BRICK PROPOSED GLAZED ROOF PROPOSED GLAZED PERIMETER FLAT ROOF PROPOSED STRUCTURAL CONCRETE COLUMNS PROPOSED DECK AND GALLERY STRUCTURE PROPOSED GLAZED BALUSTRADE WITH BRONZE HANDRAIL PROPOSED NEW OPENINGS
EXISTING OPENINGS ORIGINAL GLAZED PIER TO BE CAREFULLY CUT BACK TO ALIGN WITH ADJACENT SURFACE. REFER TO DRAWINGS 476 & 477 FOR FINISHES. NOTES: White the second of the 1. FOR REPAIRS & REMEDIAL WORK TO ALL EXTERNAL DOORS. WINDOWS, FACADE, RAINWATER GOODS AND STONE FEATURES REFER TO DRAWINGS AND SPECIFICATIONS BY DONALD INSALL ASSOCIATES LG32-1 LOUVRE/GRILLES TAGS REFER 28731-SOAS-A-SHL-GEN-XX-918 W-LG32-1 WINDOW TAGS 02.09.15 AMENDMENTS TO EXISTING CONDITION AND SCOPE OF WORKS FOLLOWING SITE SURVEY AS HIGHLIGHTED. ISSUED FOR PLANNING DISCHARGE OF CONDITION LBC 6 (j) 14.04.15 ELEVATIONS RENAMED 05.11.14 CONSTRUCTION ISSUE. RWP CAGES WEST ELE. OMITTED. LEVELS CHANGED DESCRIPTION PROJECT STATUS CONSTRUCTION **GRAHAM** CONSTRUCTION IIImace 155 Moorgate, London, EC2M 6XB www.macegroup.com SOAS INTO SENATE HOUSE MALET STREET LONDON, WC1E 7HU DRAWING TITLE PROPOSED EAST & WEST **COURTYARD ELEVATIONS** 

@ A1 C 3

1 of 1 1:100

UNRESTRICTED