



01: Front elevation – general view



02: Front elevation – shop front of Lloyds bank incorporating powder coated aluminium door and windows



03: Front elevation – main entrance to serviced offices



04: Front elevation – powder coated aluminium windows to ground floor



05: Front elevation – powder coated aluminium windows to ground floor



06: Front elevation – timber sliding sash windows to 1st, 2nd and 3rd floors



07: Front elevation – timber sliding sash windows to 1st, 2nd and 3rd floors



08: Front elevation – existing aluminium sliding windows to 4th floor mansard situated behind parapet wall



09: Front elevation – existing aluminium sliding windows to 4th floor situated behind parapet wall



10: Front elevation – showing semi circular window at high level and render above



11: Front elevation – frost shattered brickwork below rendering and around semi circular window



12: Rear elevation – general view



13: Rear elevation - timber sliding sash windows to lower ground and ground floors



14: Rear elevation – general view



15: Rear elevation - timber sliding sash windows to ground, 1st, 2nd and 3rd floors



16: Rear elevation - metal framed windows to lower ground and ground floors



17: Rear elevation - timber sliding sash windows to ground, 1st, 2nd and 3rd floors



18: Rear elevation - existing aluminium sliding windows to 4th floor mansard roof



19: Rear elevation - existing aluminium sliding windows to 4th floor mansard roof



20: Rear elevation - existing aluminium sliding windows to 4th floor mansard roof



21: Rear elevation - existing aluminium sliding windows to 4th floor mansard roof



22: Front elevation – internal view of existing sliding windows to 4th floor with secondary glazing



23: Front elevation – internal view of existing sliding windows to 4th floor with secondary glazing



24: Rear elevation – internal view of existing sliding windows to 4th floor



25: Rear elevation – internal view of existing sliding windows to 4th floor