

Photographic Record for External & Internal Refurbishment Works

at

45 New Oxford Street & 15-16 West Central Street London WC1A

for

Fred Hill Properties Limited

Prepared By:

Richard Budd BSc DipBldgCons(RICS) MRICS


Orbit Facilities Management | Wellington House | 31 - 34 Waterloo Street | Birmingham B2 5TJ Tel: 0121 643 6644 Fax: 0121 631 1881 E-mail: richard.budd@orbitproperty.com

Date: October 2015



Description

The property comprises a two and three storey building at the corner of New Oxford Street and West Central Street, with a Bookmakers on part of the ground floor, and a variety of office uses on the remainder of the floor, and upper floors.



Construction

The building was traditionally constructed, with a series of pitched slate roofs behind a parapet wall or ornamental balustrade, and solid masonry external walls with a rendered finish. The windows were a combination of painted single glazed timber vertical sliding sash pattern, or painted steel 'Crittall-style' single glazed casement pattern. The external doors were of painted timber panelled design generally.



Front Elevation (New Oxford Street)





Front Elevation – Shop Fascia level











Front Elevation – Second Floor left hand side – flaking decoration & cement render



Front Elevation – Second Floor & First Floor – flaking decoration & cement render











Front Elevation – Ground Floor – flaking decoration and sub-fluorescence to plinth. Paint-obscured vermiculated render panels.







Front Elevation – low level - flaking decoration and sub-fluorescence to plinth. Paint-obscured vermiculated render panels.











Front Right Hand Corner - flaking decoration. Paint-obscured vermiculated render panels.











Right Hand Side Elevation - 3-Storey Section (West Central Street)





Right Hand Side Elevation – Second & First Floor - flaking decoration and cracking at window heads.











Right Hand Side Elevation – First & Ground Floor - flaking decoration and cracking at window heads.









Right Hand Side Elevation – Ground Floor







Right Hand Side Elevation – 2-Storey Section - flaking decoration and cracking at window heads. Paint-obscured vermiculated render panels.








Right Hand Side Elevation – First Floor – flaking decoration and staining to projecting string course.



















Right Hand Side Elevation – cracking to window heads and plinth. Flaking decorations.









Right Hand Side Elevation - cracking and weed growth to plinth. Flaking decorations.











Right Hand Side Elevation - cracking and weed growth to plinth. Flaking decorations. Paint-obscured vermiculated render panels.










Right Hand Side Elevation - Flaking decorations. Paint-obscured vermiculated render panels.







Right Hand Side Elevation - Flaking decorations. Cracking to door heads. Paint-obscured vermiculated render panels.











Right Hand Side Elevation – flaking decorations. Cement render at second floor level.









Right Hand Side Elevation







Right Hand Side Elevation







Right Hand Side Elevation







Right Hand Side Elevation





