



- 1. Welsh slate roof with lead flashing to parapet
- 2. Render walls painted off white
- 3. Evalon by Alwitra single ply membrane roof
- 4. Lead covered lift overrun
- 5. PV array
- 6. Metal rainwater goods painted 'off white' Longbottom Ltd 4" downpipe
- 7. Hardwood timber door
- 8. Painted metal acoustic louvres
- 9. Reclaimed York stone open jointed pavers on suitable bed to permit free drainage
- 10. For planting see planting schedule
- 11. Openable glazed rooflights
- 12. Obscured tilt and turn sidelights with painted finish to hardwood frame
- 13. Garden wall repointed, repaired or replaced as necessary to match existing
- 14. Existing holly tree retained

- 17. Decorative jointing to stucco to detail
- 19. Decorative stucco cornicing

- 21. Portland stone cill
- 22. Render with lead dressing parapet
- 23. Clay chimney pots square base
- 26. Yellow London stock brick to match others locally
- 27. Hardwood framed glazed door painted
- 28. Boiler flue




- 16. Double glazed painted finished hardwood sash windows
- 18. Metal balustrade painted with metal based gloss paint
- 20. Lead clad dormer window cheeks timber front face
- 24. Electrically operated sliding gate. Metal gate to be painted
- 25. Metal garden gate painted with suitable metal gloss paint

- 29. Kitchen extract
- 30. Painted hardwood timber gate
- 31. SUDS technology to front garden landscaping
- 32. External refuse in secure enclosure
- 33. Composting bins
- 34. Secure cycle storage
- 35. Portland stone coping
- 36. Portland stone steps
- 37. Painted stucco window surrounds
- 38. For details of below ground construction see Structural Engineer's reports
- 39. For details of soil and groundwater conditions see Structural Engineer's reports
- 40. For details of services see Services Engineer's reports
- 41. Lead lined roof to minimum falls
- 42. Pool extract

| 0 |) | | | | | - | 10 20 |)m |
|---|---|--|--|---|-------|---|-------|----|
| | | | | - | - | | | |
| | | | | | | | | |

| Be | n Pentreath | h & Associ | ates |
|----------------|---|---------------------------|--------------------|
| 49 Lambs Condu | it St, London WC1N 3NC | G telephone 0207 430 2424 | 4 benpentreath.com |
| Project: | NORFOL | K ROAD | |
| | CAMDEN | 1 | |
| Title: | PROPOS | ED FRONT | Г |
| | STREET | ELEVATI | O N |
| Drwg No: | 108 | Rev. No: | D |
| Scale: | 1:100@A1 1:200@A3 | Drawn by: | AB |
| Date: | 10.15 | Checked by: | BP |
| | Pentreath Ltd/Ben Pentreath red without permission | & Associates 2014 | |



- 2. Render walls painted off white
- 3. Evalon by Alwitra single ply membrane roof
- 4. Lead covered lift overrun
- 5. PV array
- 6. Metal rainwater goods painted 'off white' Longbottom Ltd 4" downpipe
- 7. Hardwood timber door
- 8. Painted metal acoustic louvres
- 9. Reclaimed York stone open jointed pavers on suitable bed to permit free drainage
- 10. For planting see planting schedule
- 11. Openable glazed rooflights
- 12. Obscured tilt and turn sidelights with painted finish to hardwood frame
- 13. Garden wall repointed, repaired or replaced as necessary to match existing
- 14. Existing holly tree retained

- 16. Double glazed painted finished hardwood sash windows
- 17. Decorative jointing to stucco to detail
- 18. Metal balustrade painted with metal based gloss paint
- 19. Decorative stucco cornicing
- 20. Lead clad dormer window cheeks timber front face
- 21. Portland stone cill
- 22. Render with lead dressing parapet
- 23. Clay chimney pots square base
- 24. Electrically operated sliding gate. Metal gate to be painted
- 25. Metal garden gate painted with suitable metal gloss paint
- 28. Boiler flue

- 26. Yellow London stock brick to match others locally
- 27. Hardwood framed glazed door painted

- 30. Painted hardwood timber gate
- 31. SUDS technology to front garden landscaping
- 32. External refuse in secure enclosure
- 33. Composting bins
- 34. Secure cycle storage
- 35. Portland stone coping
- 36. Portland stone steps
- 37. Painted stucco window surrounds
- 38. For details of below ground construction see Structural Engineer's reports
- 39. For details of soil and groundwater conditions see Structural Engineer's reports
- 40. For details of services see Services Engineer's reports
- 41. Lead lined roof to minimum falls
- 42. Pool extract

| C |) | | | | | 5 | 10m |
|---|---|--|--|--|--|---|-----|
| | | | | | | | |
| | | | | | | | |

| Be | n Pentreatk | o & Associ | ates |
|----------------|--|-------------------------|--------------------|
| 49 Lambs Condu | it St, London WC1N 3NG | telephone 0207 430 2424 | 4 benpentreath.com |
| Project: | NORFOL | K ROAD | |
| | C A M D E N | | |
| Title: | P R O P O S E | ED FRON' | Г |
| | SOUTH E | LEVATIO |) N |
| Drwg No: | 109 | Rev. No: | D |
| Scale: | 1:50@A1 1:100@A3 | Drawn by: | AB |
| Date: | 10.15 | Checked by: | BP |
| 0 | Pentreath Ltd/Ben Pentreath ed without permission | & Associates 2014 | |



- 1. Welsh slate roof with lead flashing to parapet
- 2. Render walls painted off white
- 3. Evalon by Alwitra single ply membrane roof
- 4. Lead covered lift overrun
- 5. PV array
- 6. Metal rainwater goods painted 'off white' Longbottom Ltd 4" downpipe
- 7. Hardwood timber door
- 8. Painted metal acoustic louvres
- 9. Reclaimed York stone open jointed pavers on suitable bed to permit free drainage
- 10. For planting see planting schedule
- 11. Openable glazed rooflights
- 12. Obscured tilt and turn sidelights with painted finish to hardwood frame
- 13. Garden wall repointed, repaired or replaced as necessary to match existing
- 14. Existing holly tree retained

- 17. Decorative jointing to stucco to detail
- 19. Decorative stucco cornicing
- 21. Portland stone cill
- 22. Render with lead dressing parapet
- 23. Clay chimney pots square base
- 24. Electrically operated sliding gate. Metal gate to be painted


- 28. Boiler flue

- 15. Level access to dwelling for Lifetime Homes standards
- 16. Double glazed painted finished hardwood sash windows
- 18. Metal balustrade painted with metal based gloss paint
- 20. Lead clad dormer window cheeks timber front face
- 25. Metal garden gate painted with suitable metal gloss paint
- 26. Yellow London stock brick to match others locally
- 27. Hardwood framed glazed door painted


- 29. Kitchen extract
- 30. Painted hardwood timber gate
- 31. SUDS technology to front garden landscaping
- 32. External refuse in secure enclosure
- 33. Composting bins
- 34. Secure cycle storage
- 35. Portland stone coping
- 36. Portland stone steps
- 37. Painted stucco window surrounds
- 38. For details of below ground construction see Structural Engineer's reports
- 39. For details of soil and groundwater conditions see Structural Engineer's reports
- 40. For details of services see Services Engineer's reports
- 41. Lead lined roof to minimum falls
- 42. Pool extract

| 0 | | | | | 1 | 5 | 10m |
|---|--|--|--|--|---|---|-----|
| 1 | | | | | | | |
| 1 | | | | | | | _ |
| - | | | | | | | |
| | | | | | | | |

| | n Pentreath | | |
|----------------------------|--|---------------------|--------------------|
| 49 Lambs Condu Project: | N O R F O L C A M D E N | KROAD | 4 benpentreath.com |
| Title: | | ED REAR Elevatio | O N |
| Drwg No: | 110 | Rev. No: | D |
| Scale: | 1:50@A1 1:100@A3 | Drawn by: | AB |
| Date: | 10.15 | Checked by: | BP |
| | Pentreath Ltd/Ben Pentreath ed without permission | & Associates 2014 | |



| (|) | | | | | | 5 10 |)m |
|---|---|--|--|--|--|---|------|----|
| | | | | | | - | | |
| | | | | | | | | , |



- 1. Welsh slate roof with lead flashing to parapet
- 2. Render walls painted off white
- 3. Evalon by Alwitra single ply membrane roof
- 4. Lead covered lift overrun
- 5. PV array
- 6. Metal rainwater goods painted 'off white' Longbottom Ltd 4" downpipe
- 7. Hardwood timber door
- 8. Painted metal acoustic louvres
- 9. Reclaimed York stone open jointed pavers on suitable bed to permit free drainage
- 10. For planting see planting schedule
- 11. Openable glazed rooflights
- 12. Obscured tilt and turn sidelights with painted finish to hardwood frame
- 13. Garden wall repointed, repaired or replaced as necessary to match existing
- 14. Existing holly tree retained

- 19. Decorative stucco cornicing
- 20. Lead clad dormer window cheeks timber front face
- 21. Portland stone cill
- 24. Electrically operated sliding gate. Metal gate to be painted
- 25. Metal garden gate painted with suitable metal gloss paint
- 26. Yellow London stock brick to match others locally
- 28. Boiler flue

- 15. Level access to dwelling for Lifetime Homes standards
- 16. Double glazed painted finished hardwood sash windows
- 17. Decorative jointing to stucco to detail
- 18. Metal balustrade painted with metal based gloss paint
- 22. Render with lead dressing parapet
- 23. Clay chimney pots square base
- 27. Hardwood framed glazed door painted

- 29. Kitchen extract
- 30. Painted hardwood timber gate
- 31. SUDS technology to front garden landscaping
- 32. External refuse in secure enclosure
- 33. Composting bins
- 34. Secure cycle storage
- 35. Portland stone coping
- 36. Portland stone steps
- 37. Painted stucco window surrounds
- 38. For details of below ground construction see Structural Engineer's rep
- 39. For details of soil and groundwater conditions see Structural Engineer
- 40. For details of services see Services Engineer's reports
- 41. Lead lined roof to minimum falls
- 42. Pool extract

| (|) | | | | | 1 | 5 | 10m |
|---|---|--|--|--|--|---|---|----------|
| | | | | | | | | <u> </u> |
| | | | | | | | | |

| | FL 44.80 | | |
|----------------------------|----------------------|-----------------|-------------------------------|
| G FFL 44.45 | FL 44.80 | | |
| G FFL 44.45 | FL 44.80 | | |
| G FFL 44.45 | FL 44.80 | | |
| G FFL 44.45 | FL 44.80 | | |
| G FFL 44.45 | FL 44.80 | | |
| G FFL 44.45 | FL 44.80 | | |
| G FFL 44.45 | FL 44.80 | | |
| G FFL 44.45 | FL 44.80 | | |
| G FFL 44.45 | 1 44.80 | | |
| G FFL 44.45 | 1 44.80 | | |
| G FFL 44.45 | ⁻ L 44.80 | | |
| G FFL 44.45 | 1L 44.80 | | |
| G FFL 44.45 | FL 44.80 | | |
| | | | |
| 10. | | | |
| | | | |
| | | | |
| | | | |
| | | | Associates |
| 49 Lambs Condu Project: | | OLK RO | 207 430 2424 benpentreath.com |
| Title: | PROP SECT | OSED Ion A-A | |
| Drwg No: | 112 | Rev. N | |
| Scale: | | I | Vo: D |
| Date: | 1:50@A1 1:100@A3 | Draw | |