

There is a risk of injury or death in construction if the works are not properly planned and supervised. The contractor must not undertake any element of the work without first having carried out the necessary risk assessments and prepared detailed method statements.

Lead Clad dormer windows.

22 Portland stone cill.
23 Portland stone parapet.

Portland stone chimney flue cap.
 Electrically operated sliding gate. Gate to be black painted metal.
 Metal garden gate painted black with suitable metal gloss paint.

(26) Metal garden gate painted black with suitable metal gloss paint.
(27) Yellow London stock brick.
(28) Portland stone chimney breast.
(29) Brick voussoris in yellow london stock.
(30) Cartilevered concrete planters with painted render finish.
(31) Silding folding double glazed screens in bronze finished hardwood to achieve 1.2 W/m2K.
(32) External wall to achieve 8DB improvment over current Building Regulations;Part E.

(43) Decorative vermiculation to window surround to detail
(44) For details of below ground construction see Structural Engineer's reports (45) For details of soil and ground water conditions see Structural Engineers reports

For details of services see Services Engineers reports
 Lead lined roof to minimum falls to achieve u value of 0.1 W/m2k.

(48) External wall. no. revision.

SECOND FLOOR dwg: PROPOSED

4 BED OPTION

2724

dwg. type: PRELIMINARY dwg. status: DRAFT drawn by SRH checked by NC 1:50 at A1 size

P204

SK K

architects

Barrett Lloyd Davis Associates Ltd. 535, Kings Road, London, SW10 0SZ

Tel: 020 7838 5555 Fax: 020 7838 5556 e-mail: mail@blda.co.uk www.blda.co.uk