

Site Visit Date: 26.11.2015



Front Elevation



Close up of front elevation showing window header with historic settlement..

Site Visit Date: 26.11.2015



Front elevation from ground floor



Rear elevation showing areas which have been repaired or rebuilt.

Rear Staircase

Site Visit Date: 26.11.2015



Landing at second floor with narrow crack.



Landing at second floor showing settlement

Site Visit Date: 26.11.2015



Minor crack in wall above staircase at second floor level



Spine wall at second floor showing direction of settlement towards left hand side

Site Visit Date: 26.11.2015



Second floor ceiling showing direction of slope of joists above



Elevation of third floor spine wall showing direction of floor slope