

View of Colonnade looking West



View of Colonnade looking East



Photo of Colonnade oak timber frame looking East



Photo of typical bay



View of Colonnade and Belvedere from South

HILL GARDEN PERGOLA OAK FRAMEWORK
Photos of Colonnade as Existing

2253-01/05/01
April 2016






Photo of West end of Colonnade and Belvedere



View of Colonnade of North



Access to Colonnade from North



View of steps up to Belvedere, South side



Access opening to Colonnade from North




Photo showing vegetation in area South of Belvedere, between Colonnade steps and railings



Photo showing primary timber frame connection to Belvedere wall
*note crack on stone cornice and brick masonry below



Photo showing timber decay to primary and secondary frame along
North boundary brick wall



Photo showing timber decay to primary and secondary frame and
stone capital corrosion



Photo showing timber decay to primary and secondary frame,
rusted iron bolt and inadequate lead sheet above capital



Primary oak frame decay at North-East end corner of Colonnade



Primary oak frame decay at South-East end corner of Colonnade

HILL GARDEN PERGOLA OAK FRAMEWORK

Photos of oak frame and stone capitals defects

2253-01/05/03
April 2016

