








Existing shop front

Existing threshold and frame chipped requires weather sealing

Chipped paint to framework

Repair required to patch up old signage locations









Clean and make good to framework and windows 
Low level paint chipped at entry point







PT02-601









EXISTING DOWN LIGHTERS TO BE REMOVED AND REPLACED WITH NEW EXTERNAL BRASS FITTING. LUMINOUS INTENSITY: 780 CD, LUMINOUS FLUX 300 LM.

EXISTING UPLIGHT FITTING LAMPS TO BE REMOVED AND REPLACED WITH NEW WARMER LAMPS. LUMINOUS EFFICIENCY: 75 LM/W BLACK HANGING BRACKET FIXED BACK TO EXISTING SHOP FRONT.

EXTERNAL LED ILLUMINATION TO MATCH NEW DOWN LIGHT'S COLOR TEMPERATURE.

NEW 25 MM POWDER COATED BLUE PROJECTING SIDE PANEL.

NEW BRASS 6 MM LETTERING PINNED TO NEW FASCIA BOARD. LETTER TO BE ILLUMINATED BY LIGHTING ABOVE.

SIGNAGE PAINTED DIRECTLY ONTO EXISTING FASCIA.

PROJECTING SIGN BOX.

02\_DETAIL SCALE 1:10 @ A3