

## WS01 Back window

### Living room 02

WS01 Existing rear window to be completely refurbish and single panel of glass to be replaced with slimline double glazing;



Outside View



Inside View

## WS02 Back window

### Living room 01

WS02 Existing rear/side window to be completely refurbish and single panel of glass to be replaced with slimline double glazing;



Outside View



Inside View

## WS05 Front central window

### Bedroom A 04

WS05 Existing timber central front window is in particularly poor condition so to be replaced. The new window will be a replica of the existing in timber with slimline double glazing;



Outside View



Inside View



WS07 Side little window  
Bedroom B 05

WS07 Little window to be replace.



Outside View



Inside View

## WS08 Side window

Bedroom B 05

WS08 Existing Side Timber window \_to be completely refurbish and single panel of glass to be replaced with slimline double glazing;



Outside View



Inside View

## WS10 back window

### Bedroom C 06

WS10 Existing rear/side timber window to be completely refurbish and single pane of glass to be replaced with slimline double glazing;



Outside View



Inside View



## WS11 back window

### Bedroom C 06

WS11 Existing rear timber window \_to be completely refurbish and single panel of glass to be replaced with slimline double glazing;



Outside View



Inside View

## WS12 Side window Bedroom C 06

WS12 Existing rear/side timber window to be completely refurbish and single panel of glass to be replace with slimline double glazing;



Outside View



Inside View



## WS13 Back window

En-suite 07 – Bathroom 08

WS13 Existing rear timber window to be completely refurbish and single panel of glass to be replaced with slimline double glazing;



Outside View



Inside View