




TOP LEFT: WINDOW W-G06-1
 TOP MIDDLE: TOP OF WINDOW
 TOP RIGHT: WINDOW IRONMONGERY
 MIDDLE LEFT: TIMBER SURROUND
 MIDDLE: EXISTING IRONMONGERY
 MIDDLE RIGHT: WINDOW DETAIL



COURTYARD SIDE



STAIR 9 SIDE
 PROTECTIVE FILM STILL ON WHITE FRAME



ABOVE: SLOTS TO TIMBER CILL
 BELOW: UNDERSIDE OF EXISTING
 TIMBER WINDOW CILL



EXISTING WINDOW TO W-G06-1
 SINGLE GLAZED

FORSTER 30 MINUTE SECONDARY
 GLAZING INSTALLED TO STAIR 9

© COPYRIGHT Mace Group
 NOT TO BE REPRODUCED WITHOUT WRITTEN PERMISSION.
 BECAUSE OF POSSIBLE SCALING ERRORS IN ELECTRONIC AND HARDCOPY
 REPRODUCTION DO NOT SCALE FOR CONSTRUCTION PURPOSES.
 ALL DIMENSIONS TO BE CHECKED & VERIFIED ON SITE PRIOR TO CONSTRUCTION.

Safety first. Second nature.

Safety, Health and Environmental Information

The significant unusual hazards / risks associated with this type of work are noted as:

CONSTRUCTION	
DI	
CI	
OPERATION AND MAINTENANCE	
DI	
CI	
DISMANTLING/ DEMOLITION	
DI	
CI	

NOTE - TO BE READ IN CONJUNCTION WITH THE COM RISK REGISTER

REV	DATE	DESCRIPTION	DRAW	CHK

KEY PLAN

PROJECT STATUS: SKETCH

CLIENT

mace
 155 Moorgate, London, EC2M 6XB
 www.macegroup.com

PROJECT TITLE
 SOAS INTO SENATE HOUSE
 MALET STREET
 LONDON, WC1E 7HU

DRAWING TITLE
 Existing window G06
 Precedent install - Stair 9

PROJECT NO.	DRAWN BY	XX	DATE	XX.XX.XX
28731	CHK BY	XX	DATE	XX.XX.XX
	APPD. BY	XX	DATE	XX.XX.XX

28731-SOAS-A-SKE-XXX-XX-162

SHEET NO.	SCALE	ORIG. SHEET SIZE	REV.
1 of 1	VAR	@ A1	-

INFORMATION HANDLING CLASSIFICATION
 UNRESTRICTED

selectsize.dwg