

Existing/Photographs

Lower Ground Floor Rear Detail



Second floor facing east roof detail.



LGF extension door with the same style security glass as front elevation LGF windows.



Facing north east, security gate detail.



LGF wc window.



LGF extension balcony, seen from rear garden.





LGF utility room window.



LGF utility room covered window.



LGF kitchen window 3, with security glass.



LGF extension balcony, seen from the bathroom.

