

[REDACTED]

Application No:	Consultees Name:	Consultees Addr:	Received:	Comment:	Response:
2016/3178/L	A Chandler	Ground Floor Flat 33 Arlington Road	09/06/2016 15:59:40	Q3J	The proposed replacement of the existing timber sash windows (which have slim glazing bars and match those next door at 38) with "heritage" double glazed ones is not appropriate for a Listed Building. The current windows are in suitable condition to allow them to be repaired where necessary (original sash windows at 69, 71 and 48 Arlington Road have all recently been repaired in similar circumstances and look wonderful). Should additional acoustic insulation be required then suitably designed internal secondary glazing would be appropriate in this instance.

[REDACTED]

[REDACTED]