



Image 2: Author Dr Mervyn Miller



Image 3: Author Dr Mervyn Miller

Existing condition images:

- 1) Ground floor stair off main hall.
- Stair timber largely intact. Cosmetic repair to be applied.
- Period wallpaper to be removed.
- 2) Corinthian column capital.
- Chipped stonework detailing to be repaired and replaced where applicable.
- 3) Grand hall ceiling.
- White paint over original timber to be removed and natural colour reinstated.