

Photo of seasoned English Oak sample against 1990's oak beams and joists in the Pergola extension West of the footbridge

Photo of seasoned English Oak sample against 1911 oak beams and joists in the Pergola Colonnade extension. Note existing wet timber dark colour due to rain water darkening the oak. The sample instead is completely dry oak.

HILL GARDEN PERGOLA OAK FRAMEWORK Photos of English Oak sample

