


DETAIL 1 - SECTION THROUGH LIFT SHAFT/ LIFT LOBBY
1:50



VISUAL SCALE 1:200 @ A3

3654-PL-619
PROPOSED LIFT LOBBY DETAILS

At first & second floor Building regulation require a fire curtain to be located above the lift opening that will drop down if the smoke alarm is triggered to restrict smoke entering the upper flats.
At third floor the smoke will extract through the roof so is not needed at this level.
Refer to MLM Building inspectors statement accompanying this application reference RE/8417680/MW dated 5 July 2016



James Taylor Construction