



- 1 ALL EXISTING BRICKS, HEARTHSTONES AND REQUIRED NEW STAIRS TO BE REPAIRED TO ORIGINAL CONDITION WITH CONSERVATION BEST PRACTICE
- 2 ALL CHIMNEYS TO BE RESTORED TO WORKING ORDER AND REPAIRED WHERE REQUIRED IN PRACTICE
- 3 CEILING ROOF TO BE REPAIRED TO MATCH ORIGINAL CONDITION WITH CONSERVATION BEST PRACTICE
- 4 REPAIRING AND REPAIRING TO BE RESTORED / REPAIRED AS PER ORIGINAL PATTERNS IN PRACTICE WITH CONSERVATION BEST PRACTICE
- 5 NEW CONTEMPORARY FEATURE LIGHTING IN HALLWAY AND STAIRWELL
- 6 CONTEMPORARY AND UNIFORM ACCESS SYSTEM AND WALL DOORS NEEDED TO WALLS WITHIN ENTRANCE PORCH
- 7 FLOOR JOISTS TO BE STRENGTHENED LOCALLY REQUIRED NEW STAIRS TO BE REPAIRED TO ORIGINAL CONDITION WITH CONSERVATION BEST PRACTICE
- 8 OTHER FLOORING RESTORED AND REPAIRED WHERE POSSIBLE OR NEW THIBER / STONE FLOORING
- 9 HEARTHAGE APPROVED PAINT RANGE COLOURS TO BE ACCORDANCE WITH CONSERVATION BEST PRACTICE
- 10 ORIGINAL STONE AND THIBER STAIRCASES TO BE RESTORED IN ACCORDANCE WITH CONSERVATION BEST PRACTICE
- 11 CARRIAGE ON STAIRCASE TO BE REPAIRED WITH NEW KILNDR
- 12 NEW BRICK GABLETILING WITH SLATE ROOF TO MATCH EXISTING ADJOINING BUILDING ENTRANCE PORCH
- 13 EXCAVATED ARCHES WITH LOWERED AROUND BRICKSTONE
- 14 NEW LIMESTONE FLAGSTONES
- 15 STEEL FRAMED CRITICAL GLAZING ELEMENT
- 16 NEW MASONRY TILING PATTERNS TO BE REPAIRED IN ACCORDANCE WITH CONSERVATION BEST PRACTICE
- 17 EXISTING STONE STEPS AT ENTRANCE TO BE RESTORED IN ACCORDANCE WITH CONSERVATION BEST PRACTICE
- 18 ALL ORIGINAL ROOM WINDOWS, PARTIAL THIBER WHERE REQUIRED REPAIRED TO MATCH EXISTING CONSERVATION BEST PRACTICE
- 19 ROOT TO BE RECONSTRUCTED - ALL ORIGINAL REPAIRED WITH LEAD SHEETING
- 20 NEW THIBER TILING DOWN AND REPAIRED IN ACCORDANCE WITH CONSERVATION BEST PRACTICE
- 21 PAINTWORK TO BE REPAIRED TO MATCH EXISTING WITH THE REST OF THE TERACE
- 22 NEW CAST IRON RAINWATER WHEN INEERING CONSERVATION BEST PRACTICE
- 23 WITH EXISTING
- 24 NEW OPENING IN REAR FACADE AT LOWER LEVEL WHERE REQUIRED REPAIRED TO MATCH EXISTING CONSERVATION BEST PRACTICE
- 25 NEW MASONRY WALL
- 26 EXCAVATION OF LOWER GROUND FLOOR TO BE REPAIRED AND MOVED ADEQUATE FLOOR AND PAINTED GLOSS BLACK TO MATCH ORIGINAL
- 27 NEW CAST IRON RAINWATER WHEN INEERING CONSERVATION BEST PRACTICE
- 28 NEW DOUBLE GLAZED BLACK FRAMED WINDOWS BOND AND SCOTLAND TO MATCH EXISTING
- 29 NEW MASONRY WALL
- 30 EXISTING BRICK TO BE REPAIRED AND REPAIRED TO MATCH EXISTING CONSERVATION BEST PRACTICE
- 31 EXCAVATION OF LOWER GROUND FLOOR TO BE REPAIRED AND MOVED ADEQUATE FLOOR AND PAINTED GLOSS BLACK TO MATCH ORIGINAL
- 32 NEW CAST IRON RAINWATER WHEN INEERING CONSERVATION BEST PRACTICE
- 33 NEW FIRE RATED THIBER DOOR SETS TO MATCH ORIGINAL
- 34 NEW FIRE RATED THIBER DOOR SETS TO MATCH ORIGINAL
- 35 NEW FIRE RATED THIBER DOOR SETS TO MATCH ORIGINAL
- 36 NEW FIRE RATED THIBER DOOR SETS TO MATCH ORIGINAL
- 37 NEW FIRE RATED THIBER DOOR SETS TO MATCH ORIGINAL
- 38 NEW FIRE RATED THIBER DOOR SETS TO MATCH ORIGINAL
- 39 NEW FIRE RATED THIBER DOOR SETS TO MATCH ORIGINAL
- 40 NEW FIRE RATED THIBER DOOR SETS TO MATCH ORIGINAL



NOTES

REVISION / DESCRIPTION	DATE	DATE
REV. DRAWING SUBMITTED (FIRST ISSUE)	00K	28.10.15
REV. CLOSET WALL REVISIONS (REVISION)	00K	28.10.15
REV. CLOSET WALL REVISIONS (REVISION)	00K	28.10.15

OOK ARCHITECTS SHALL HAVE NO RESPONSIBILITY FOR ANY USE OF THIS DRAWING FOR ANY OTHER PROJECTS. THE DRAWING HAS BEEN PREPARED AND ISSUED. ALL DIMENSIONS SHOULD BE CHECKED ON SITE. DO NOT SCALE FROM THE DRAWING. ANY DRAWING ERRORS SHOULD BE BROUGHT TO THE ATTENTION OF OOK ARCHITECTS.

OOK ARCHITECTS
 119 Fairfield Road
 London EC1R 3DA
 studio@ookarchitects.com
 www.ookarchitects.com

PROJECT NUMBER	PROJECT TITLE	DATE
518A	66 GUILDFORD STREET	28.10.15
DRAWING TITLE	SCALE	
Section B Proposed	1:100	
STATUS	DRAWING NO.	REVISION
PLANNING	518A-SE-211	P03