

ARBORICULTURAL METHOD STATEMENT

BS 5837: 2012

Site: 28 Lyndhurst Road, London, NW3 5PB

Presented to:

Lyndhurst Global Ltd (c/o SD Management Ltd)

By:

Landscape Planning Limited
4 The Courtyards
Wyncolls Road
Colchester
CO4 9PE

31/10/2016 Our Ref: 69039



CONTENTS

| 1.0 | EXECUTIVE SUMMARY | | | | | | | | |
|----------------------------------|--------------------|---|----|--|--|--|--|--|--|
| 2.0 | REPORT PROCEDURES5 | | | | | | | | |
| 3.0 | PREFACE | PREFACE6 | | | | | | | |
| 4.0 | PLANS A | ND REFERENCE DOCUMENTS | 6 | | | | | | |
| 5.0 | DECKING | INSTALLATION | 7 | | | | | | |
| 6.0 | THE TRE | ES | 7 | | | | | | |
| 7.0 | ARBORIC | ULTURAL IMPACT ASSESSMENT | 9 | | | | | | |
| 8.0 | CONCLUS | SIONS | 10 | | | | | | |
| 9.0 | APPENDI | CES | 11 | | | | | | |
| | ENDIX 1 | Key To Tree Tables | | | | | | | |
| | ENDIX 2 | Tree Survey Tables | | | | | | | |
| APPENDIX 3 Tree Constraints Plan | | | | | | | | | |
| APPENDIX 4 Photographs | | | | | | | | | |
| APP | ENDIX 5 | Revised Architect's Plan Showing Tree Grid Detail | | | | | | | |
| APP | ENDIX 6 | Report Caveats | | | | | | | |

1 EXECUTIVE SUMMARY

- 1.1 Historically, the Council granted Full Planning permission on 12 August 2014 [application reference 2013/7377/P], subject to a Section 106 legal agreement for:
- 1.2 "Replacement of existing rear conservatory with part 1 storey part 2 storey rear infill extension including enlargement of existing lightwell, addition of lightwell and removal of windows to east elevation all associated with creating an additional 2 bedroom dwelling"
- 1.3 The trees within the garden of No 28 Lyndhurst Road are considered as integral to the mature sylvan character in particular of the rear garden curtilage. The trees have been professionally managed over time, with the Council presenting no objections to careful and proportionate Conservation Area tree surgery management.
- 1.4 Currently, the Council have registered under 2016/3019/P:
- 1.5 "Erection of a timber deck above storage units in rear garden of dwelling house (Class C3) and installation of steel & glass balustrade and 1.8m screening in the form of camouflage netting (Retrospective)"
- 1.6 This Arboricultural Method Statement is now submitted in support of the recent installation being retrospectively considered by the Council under 2016/3019/P.
- 1.7 Various exchanges between the Council and SD Developments have led to the appointment of the Landscape Planning Group [LPG]. We have been asked to provide an arboricultural report covering aspects of the decking installation with the 1.8m screening, which is presented as live vegetation softening the eastern edge of the decking located immediately above the garden storage units.
- 1.8 A site visit was conducted by the appointed LPG Principal Consultant on 6th October 2016 in order to carry out a preparatory tree survey for the BS5837:2012 AMS.
- 1.9 The four trees in the immediate vicinity of the decking are mature trees of high amenity value. They all possess Category 'A' BS 5837 characteristics.
- 1.10 Lime T1 has never been involved in any way with the proposal under consideration.
- 1.11 The main issues can be summarised as:
 - i] demonstrating that no understorey beneath the mature trees T2 to T4 has been removed in the course of installing the decking
 - ii] the method of decking construction and installation including facilitating percolation in the immediate environs of the mature tree bases of T2 to T4

- iii] details of the live screening and how the screening is to be installed on the eastern edge of the decking
- iv] details of how the live screening will be maintained and managed
- 1.5 A summary of the affected trees is detailed in the table below:

| Impact | Reason | А | В | С | U |
|-----------------------------|---|------------------|------|------|------|
| Trees to be removed | To facilitate the development or due to their condition (U cat) | None | None | None | None |
| Trees with RPA encroachment | To facilitate installation | T2, T3 and T4 | None | None | None |
| Retained trees to be pruned | To address identified defects / facilitate construction | None | None | None | None |

Project Team Contacts List

| Name | Company | Position | Tel. No. |
|---|------------------------------------|--|--|
| Margaret MacQueen Margaret.MacQueen@oca- arb.co.uk | Landscape Planning Group Ltd | Principal Consultant Arboriculturist | T: 01206 224787 M: 07717 836594 |

2 REPORT PROCEDURES

2.1 This Report has been prepared in accordance with Landscape Planning Ltd's quality system procedures as follows:

Methodology relating to Arboricultural Impact Assessments

2.2 File creation, field survey, data capture procedures and report production follow the specific methodologies, technical approach and quality systems of Landscape Planning Ltd. The aim is to provide "fit for purpose" deliverables based on the client brief. Our approach broadly follows the guidance contained in "Trees in relation to Demolition, Design and Construction – Recommendations" (BS 5837:2012); however, the use of any terms or concepts contained therein does not imply Landscape Planning Ltd's acceptance of their accuracy or scientific validity and the use of any section or concept contained within the standard is on the principle of its advisory status as guidance.

Report and Findings

2.3 The Report and Findings have been quality checked prior to issue to the client.

Signed,

Michael Lawson

Principal Consultant

Landscape Planning Ltd

Michael Ion Ca

Dated: 31/10/2016

3 PREFACE

3.1 The Scope of Survey and Reporting

- 3.2 Landscape Planning Ltd has surveyed the key trees on the site and has provided guidance within this report on the measures necessary to ensure successful tree retention with the installed decking. The scope was as follows:
- 3.3 To visit the site and complete a survey of trees, shrubs, hedgerows and other vegetation that may materially be of interest relative to implemented proposals.
- 3.4 To assess the likely impacts of the development on the trees and make 'in principle' recommendations relating to tree removals, tree retention and tree protection during development.
- 3.5 To carry out an arboricultural impact assessment on the effect of the new development at the site.
- 3.6 To produce a tree constraints plan (TCP), showing the location of surveyed trees, their BS5837:2012 categorisation and the theoretical Root Protection Areas (RPA).
- 3.7 To make any other observations or recommendations as required based on the survey.

4 PLANS AND REFERENCE DOCUMENTS

- 4.1 BS5837:2012 'Trees in relation to design, demolition and construction recommendations'
- 4.2 BS3998:2010 'Tree work recommendations'
- 4.3 NJUG 4 National Joint Utilities Group "Guidelines for the planning, installation and maintenance of utility apparatus in proximity to trees. Volume 4, issue 2. London: NJUG 2007"
- 4.4 Information from the Council's planning website including submission made by SD Developments and their Architects.
- 4.5 We understand that the scheme is currently being considered for planning permission.

5 DECKING INSTALLATION

- 5.1 The site prior to the installation of the decking can be seen in the series of photographs at Appendix 4.
- 5.2 No existing understorey shrubbery was removed in order that the decking could be installed. The same views into rear gardens could be seen before the decking was installed.
- 5.3 Prior to the installation, a proprietary geotextile fabric was laid down, over which were located parallel with the existing garden path a series of blocks at 3000mm spacings.
- 5.4 The baton structure as can be seen in the series of photographs at Appendix 4 was effectively installed suspended above ground level so no new compaction was caused.
- 5.5 The decking that had been run too close to the trunk or stem bases of T2 to T4 will now been replaced by a 1.8m by 1.8m tree grid feature to aid percolation of rainwater (see Appendix 5 for details).
- 5.6 The topography was always gently sloping to the roofs of the garden storage units, so the eastern edge of the decking will be softened in relation to views into the rear gardens of Wedderburn Road, and in order to provide privacy in relation to residents who may equally have been walking at the far end of the rear garden, a series of planters will be used.
- 5.7 Live screening to a height of 1.8m will be provided in spaced planters, which will be both independently irrigated and subsequently managed by pruning.
- 5.8 The planters will be boxed in using the same materials as the decking to provide the best visual continuity.

6 THE TREES

- 6.1 There were 4 Individual trees surveyed on-site or immediately adjacent to the site boundary.
- 6.2 By BS 5837:2012 Categorisation, the trees can be summarised as follows:

| BS 5837 Cat | A | В | С | U |
|---------------------|----------------------|------|------|------|
| Specific Trees | T1, T2, T3 and T4 | None | None | None |
| Total Number | 4 | 0 | 0 | 0 |

6.3 These trees' locations and their visual contributions can be summarised as follows:

| BS 5837 Cat | Α | В | С |
|---|------------|---|---|
| Internal contribution to external rear garden views | T2, T3 and | | |

6.4 Our detailed check with the Local Planning Authority has confirmed that the following trees are subject to statutory protection:

| | А | В | С | U |
|-------------------|-------------------|---|---|---|
| Conservation Area | T1, T2, T3 and T4 | | | |

6.5 The site address is in the Fitzjohns Netherhall Conservation Area.

7 ARBORICULTURAL IMPACT ASSESSMENT

7.1 TREE REMOVALS

7.1.1 No trees will be removed to facilitate the decking.

7.2 ROOT PROTECTION AREA (RPA) INCURSIONS

7.2.1 The following incursions into the RPAs of trees to be retained have been identified:

| BS 5837 Cat | A | В | С | Summary |
|------------------|---------------|---|---|---------|
| No RPA Incursion | T1 | | | |
| RPA Incursion | T2, T3 and T4 | | | |

7.3 DECKING SURFACE

- 7.3.1 The proposal has already been implemented and has resulted in the decking being suspended on a baton structure, which itself is suspended above the actual ground level.
- 7.3.2 In our view, the installation has minimised the disruption on the retained trees; the surface sits above ground level and no tree roots were severed during installation.

7.4 GROUND LEVELS

7.4.1 No changes to existing ground levels were proposed within the RPAs of retained trees.

8 CONCLUSIONS

- 8.1 The site is located in the Fitzjohns Netherhall Conservation Area. All four mature rear garden trees are managed to a high standard and are valued for their contribution to the sylvan character of the eastern edge of the rear garden.
- 8.2 Ground protection measures within retained tree RPAs have been used to ensure adequate protection of the RPAs whilst the decking has been installed.
- 8.3 Harmful excavations and removal of pre existing vegetation has been avoided.
- 8.4 Overall, it is concluded that the decking has been implemented without undue impact on the mature trees.
- 8.5 The project should be concluded by the installation of tree grids and the provision of the live screen at the eastern edge of the decking.

Mrydeithc Queen.

Margaret MacQueen BSc CBiol MRSB MICFor CEnv MAE

Principal Consultant Arboriculturist

OCA UK Limited

on behalf of LPG

9 APPENDICES

APPENDIX 1 Key To Tree Tables


APPENDIX 2 Tree Survey Tables

APPENDIX 3 Tree Constraints Plan

APPENDIX 4 Photographs

APPENDIX 5 Revised Architect's Plan Showing Tree Grid Detail

APPENDIX 6 Report Caveats



Key


| BS 5837 Cat | Description |
|-------------|---|
| | Those of high quality and value: in such a condition as to be able to make a |
| Α | substantial contribution (> 40 years) |
| | Those trees of moderate quality and value: those in such a condition as to |
| В | make a significant contribution (> 20 years) |
| | |
| | Those trees of low quality and value: currently in adequate condition to remain |
| С | until new planting could be established (> 10 years) |
| | |
| | Those in such a condition that any existing value would be lost within 10 years |
| U | and which should, in the current context, be removed regardless of |
| | development |
| | |

Note: Sub categories are denoted in the tree survey data (A1, B1, C2 etc.). You are referred to the BS for further detail if required.

| Tree No. | T (tree), G (group), H (hedge), W (woodland) + Ref No. |
|----------------------|--|
| Species | Common Name |
| Ht (m) | Measured height in metres |
| DBH (m) | Diameter at 1.5m above ground level |
| Branch Spread | In m to cardinal points |
| Cr Ht Clearance (m) | Overall height of lowest branches from the ground level on side of |
| | proposed development |
| Life Stage | Young, Semi-Mature, Early-Mature, Mature, Over-Mature |
| General Observations | Observations on the condition of the tree(s) |
| Tree Work | Proposed tree works in accordance with BS3998 |
| Specification | |
| BS Cat | See above |
| Life Exp | Estimated remaining contribution in years. |
| RPA Radius(m) | Radius of the trees Root Protection Area measured from the trunk to |
| | the edge of the RPA circle in metres |
| RPA (m2) | Overall Root Protection Area in m2 |
| * | Indicates where tree data may have been estimated as tree was |
| | offsite / restricted access / dense vegetation hindering full inspection |

| Age Range | YO | Trees from seedling, up to Advanced Nursery Stock size (14/16cm girth) |
|-----------|----|--|
| | SM | More than 10 years post-establishments but capable of being moved using a large tree spade (up to 22/24cm diameter). |
| | ЕМ | Early indictors of maturity in bark tissue, reproductive tissue, leaf and crown morphology may be present. (Notably, excurrent shoot growth, not readily transplantable and still likely to increase significantly in size). |
| | MA | Strong indicators of maturity in bark tissue, reproductive tissue, leaf and crown morphology will be present. Shoot growth decurrent. (Middle aged phase of growth when the tree has effectively reached up to 90% of its ultimate size for the species and location). |
| | FM | Bark tissue, reproductive tissue, leaf and crown morphology will all exhibit mature characteristics. Strongly decurrent shoot growth and reduced shoot extension. No specific signs of senescence. (A tree that has now achieved over 90% of its ultimate life for the species and location). |
| | ОМ | Trees in senescence. Although not directly in decline from disease, decay, root death, structural or stability. Problems are primarily resulting from old age. (Senescence is an age related category, i.e. a younger tree subject to disease and decay because of, for example, an impact injury would not be senescent. Characteristically, senescent trees are likely to be reducing in mass and becoming stag headed. |

Job ref: JobReference




ARBORICULTURAL IMPACT ASSESSMENT TREE SURVEY TABLES

Surveyor: Margaret MacQueen Date Surveyed: 06 October 2016


28 Lyndhurst Road



| Tree No. | Species (English) Latin if any doubt | Age Range | Height (m) | C | | adius (n - E – W | n) | Stem Diam @ 1.5m (mm) | BS RPR (m) | Comments (incl. Structural condition) | Recommendations | Remaining contribution (Yrs) | Amenity |
|----------|--|-----------|------------|---|----|---------------------|----|--------------------------|------------|---|-----------------|------------------------------------|---------|
| T1 | Lime (Large leafed) | Mature | 25 | 4 | 5 | 4 | 3 | 800 | 9.6 | Average to good form, shape and condition. Subject to historic crown management - lifted and thinned. Dense crown, low crown dead wood. Tree located near to edge of rear garden. | No works. | 40+ | Α |
| T2 | Plane (London) | Mature | 24 | 8 | 10 | 5 | 4 | 950 | 11.4 | Good form, shape and condition. Subject to historic crown management – lifted and thinned. Tree located within decking. | No works. | 40+ | А |
| Т3 | Horse Chestnut | Mature | 23 | 6 | 10 | 6 | 5 | 1050 | 12.6 | Average to good form, shape and condition. Subject to historic crown management – lifted and thinned. Tree located within decking. | No works. | 20- 39 | А |
| T4 | Horse Chestnut | Mature | 23 | 8 | 3 | 5 | 4 | 850 | 10.2 | Average to good form, shape and condition. Subject to historic crown management – lifted and thinned. Tree located within decking. | No works. | 20- 39 | А |



| Troc No. Species DRH(m) No of Ht (m) BS Cot | | COPYRIGHT RESERVED DO NOT SCALE FROM THIS DRAWING |
|---|--|---|
| T1 Lime (Large leafed) 0.8 1 25 A2 | | Tree Survey Drawing Key |
| T2 Plane (London) 0.95 1 24 A1 T3 Horse Chestnut 1.05 1 23 A2 T4 Horse Chestnut 0.85 1 23 A2 | | Root Protection Area m2 Tree Canopy Extent Stem Location / Coloured disc |
| 14 Horse Officiality 0.00 1 20 712 | | Stem Location / Coloured disc denotes BS: 5837 Category Tree Number |
| | | See Landscape Planning Tree Survey for Individual Tree Details |
| | | KEY Please refer to Landscape Planning arboricultural report for details |
| | | Category A - high quality and value Category B - moderate quality and value Category C - low quality and value Category U - removal |
| | A97 A98 A98 A98 A98 | RPA - root protection area as defined by Table 2 BS 5837:2012 |
| | And | Category U - removal |
| | | |
| no.27 | | |
| | pris para free T3 | |
| | m/oncio m/onci | |
| upon to Rigar below me for reprod | poord 3 | |
| | T2 OT A1 | |
| no.28 | graph to the state of the state | |
| | The great tests tests to the state of the st | |
| a to the field to | | |
| | ands two less tools tool | |
| | A2 | |
| no.29 | | |
| | | DEVICIONO |
| | APA RPA RPA RPA | REVISIONS No Description By Date Chkd |
| | | |
| | | |
| | | LANDSCAPE PLANNING LTD |
| | | ISSUE: |
| | | CLIENT: Lyndhurst Global Limited LOCATION: |
| | | 28 Lyndhurst Road, London NW3 5PB DRAWING TITLE: |
| | | Tree Constraints Plan (TCP) |
| | 2m 0 10m 20m scale bar 1:250 | SCALE: 1:250 @ A3 DATE: 10th October 2016 |
| | | © Crown Copyright. All rights reserved. Licence number 100043594 |



Photographs Taken By Margaret Macqueen on the 06 October




Photographs Supplied by Architect on Construction of Decking





Photographs of Rear Garden Prior to Decking Installation



Looking towards T1 and T2







General - Trees

Unless otherwise stated tree observations have been undertaken from ground level and using non-invasive techniques only. Comments contained within the report on the condition and risk associated with any tree relate to the condition of the tree at the date and time of survey. Please note that the condition of trees is subject to change. This change may occur, but is not limited to biological and non-biological factors as well as mechanical/physical changes to conditions in the proximity of the tree. Trees should be inspected at intervals relative to identified site risks and in accordance with relevant HSE and Central Government guidance. Landscape Planning Group Ltd can provide further information on this matter if required.

Unless otherwise specified, no checks have been carried out in respect of statutory controls that may apply, e.g. Tree Preservation Orders, Conservation Areas or planning conditions. In addition, prior to undertaking any tree works, it is necessary to ensure due diligence is followed in respect of protected species and habitats.

Where tree surgery works have been identified these works are based on the assumption that planning is approved, no tree works should be undertaken prior to determination of this application without up to date confirmation of the Tree Preservation Order / Conservation Area Status of the vegetation. All works should be undertaken in accordance with the appropriate Duty of Care. This should include, for example, site specific risk assessments and due diligence inspections for the presence of protected species.

Any comment relating to 3rd party trees has been made without full access to the tree(s). Should these trees have any impact on the proposed development we would advise you to instruct us to contact the 3rd party and undertake further inspection work.

Copyright & Non-Disclosure Notice

The content and layout of this report are subject to copyright owned by Landscape Planning Group Ltd save to the extent that copyright has been legally assigned to us by another party or is used by Landscape Planning Ltd Group under license. This report may not be copied or used without our prior written agreement for any purpose other than the purpose indicated in this report.

Third Party Disclaimer

Any disclosure of this report to a third party is subject to this disclaimer. The report was prepared by Landscape Planning Ltd at the instruction of, and for the use by, our client named within the report. This report does not in any way constitute advice to any third party who is able to access it by any means. Landscape Planning Group Ltd excludes to the fullest extent lawfully permitted all liability whatsoever for any loss or damage arising from reliance on the content of this report.

Not a Design Statement or Method Statement

This report has been prepared in respect of development impacts on trees. The report provides details and makes in principle recommendations relating to tree protection, which may have implications for design, construction, materials and methods to be employed in the development. Any such recommendations should be approved by the relevant designer / competent person.



Landscape Planning Limited
4 The Courtyards
Phoenix Square
Wyncolls Road
Colchester
Essex CO4 9PE

01206 752539

Info@landscapeplanning.co.uk

www.landscapeplanning.co.uk