

TYPICAL SASH WINDOW bottom rail detail



SASH WINDOW REPAIR incorrect bottom rail detail to be rectified

© 2016 Syte Architects Limited

drawing is copyr

use figured dimensions - do not scale dimensions from drawing
if the drawing exceeds the quantities in any way the architects are to
informed before work is commenced

drawing to be read in conjunction with structural engineer's drawin specification

INFORMATION ISSUE

revision notes



en Golden Square London W1F 9JA T 020 7734 8310 www.sytearchitects.com

client

Andrew & Sukey Brecher

proje

43 Cumberland Terrace London NW1 4HP

drawing title

Window Existing Window Photographs

 Nov 2016
 SP
 P1

 scale
 checked by
 drawing

 /
 OB
 270.411