

APPENDIX E

Exploratory hole logs

Foundation Inspection Pits (FIPs) Photo Sheets



View of concrete foundation encountered in FIP01



View of Made Ground and concrete footing in FIP01



View of arisings excavated from FIP01




View of FIP02 showing concrete foundation encountered



View of FIP02



View of arisings from FIP02

Client Fairview Ventures Limited	Project Centric Close, Camden	Job No CG/18804A
	Title Foundation Inspection Pits	Appendix E



View of concrete foundation in FIP03



View of concrete foundation in FIP03



View of arisings from FIP03




View of FIP04



View of concrete foundation in FIP04



View of arisings from FIP04

Client Fairview Ventures Limited	Project Centric Close, Camden	Job No CG/18804A
	Title Foundation Inspection Pits	Appendix E

Foundation Inspection Pits (FIPs) Photo Sheets



View of concrete foundation encountered in FIP01



View of Made Ground and concrete footing in FIP01



View of arisings excavated from FIP01




View of FIP02 showing concrete foundation encountered



View of FIP02



View of arisings from FIP02

Client Fairview Ventures Limited	Project Centric Close, Camden	Job No CG/18804A
	Title Foundation Inspection Pits	Appendix E



View of concrete foundation in FIP03



View of concrete foundation in FIP03



View of arisings from FIP03




View of FIP04



View of concrete foundation in FIP04



View of arisings from FIP04

Client Fairview Ventures Limited	Project Centric Close, Camden	Job No CG/18804A
	Title Foundation Inspection Pits	Appendix E