



Non original mirrored glass glued to surface of cupboard. Very difficult to remove glass without damaging the wood panels behind.



Warped doors and chips around door frame



Non original slats and patching work has been carried out on the cupboard, which is unsightly and has caused cracking.