

PROPOSED LOWER NORTH ELEVATION

## REPAIR WORK KEY



Stonework - Repair


Brickwork - Repair.

Repointing - Rake out and repoint to match existing.


Stained area to be cleaned.

Any type of fitting to be removed and brickwork made good.

Render - Repair




Cornice - Repair



## TYPICAL WINDOW - OUTWARD OPENING (based on Ideal Combi FUTURA+)

- Made of Timber | PUR | Aluminium
- Slim 53mm aluminium profiles
- Double glazed units.
- 149mm frame (typical Ideal Combi Futura+ or similar)
- 160mm brick reveal which allows internal return of 56mm



3D VIEW OF SLIP CILL BEDDING

**S01** - SECTION THROUGH TYPICAL WINDOW 1:20@A3

(GL

