

## Report in support of mechanical ventilation removal to Galleries 43 and 45



View of ductwork serving Galleries 43-45





After removal of ductwork



Ibstock London White glazed bricks selected as a close match






View from inside gallery after duct removed




The completed glazed brick works





Detail at north end of lightwell - existing condition and works carried out





Detail at south end of lightwell - existing condition and works carried out