

Project: Centre Point  
 Client: Multiplex  
 Title: Mosaic Tiles

Date:  
 Job No. 15027  
 App :



Column	Elevation	Floor	Item	Description Of Repair	Approx. Length (mm)	Approx. Height (mm)	M2 / M3	Qty	Unit	Isolated (nr)	Patches (m2)
<b>South East Column</b>											
				<b>Ground Floor</b>							
				<b>North Elevation</b>							
South East	North	Ground	1.1	Missing Patch Tiles	0.15	0.05	0.008	0.008	m2		0.008
South East	North	Ground	1.2	Missing Patch Tiles	0.65	0.5	0.325	0.325	m2		0.325
				<b>East Elevation</b>							
South East	East	Ground	1.3	Missing Isolated Tiles				9	nr	9	
South East	East	Ground	1.4	Missing Patch Tiles	2.45	0.45	1.103	1.103	m2		1.103
				<b>West Elevation</b>							
South East	West	Ground	1.5	Missing Isolated Tiles				9	nr	9	
South East	West	Ground	1.6	Missing Patch Tiles	0.2	0.1	0.020	0.020	m2		0.020
South East	West	Ground	1.7	Missing Patch Tiles	0.06	0.3	0.018	0.018	m2		0.018
South East	West	Ground	1.8	Missing Patch Tiles	0.3	0.02	0.006	0.006	m2		0.006
South East	West	Ground	1.9	Missing Patch Tiles	0.15	0.45	0.068	0.068	m2		0.068
				<b>South Elevation</b>							
South East	South	Ground	1.10	Missing Patch Tiles	0.15	0.05	0.008	0.008	m2		0.008
South East	South	Ground	1.11	Missing Patch Tiles	0.65	0.5	0.325	0.325	m2		0.325
				<b>1st Floor</b>							
				<b>North Elevation</b>							
South East	North	Mezz	1.12	Missing Patch Tiles	0.15	0.05	0.008	0.008	m2		0.008
				<b>East Elevation</b>							
South East	East	Mezz	1.13	Missing Isolated Tiles				20	nr	20	
				<b>South Elevation</b>							
South East	South	Mezz	1.14	Missing Isolated Tiles				20	nr	20	
South East	South	Mezz	1.15	Missing Patch Tiles	0.15	0.05	0.008	0.008	m2		0.008
				<b>West Elevation</b>							
South East	West	Mezz	1.17	Missing Patch Tiles	0.2	0.1	0.020	0.020	m2		0.020
South East	West	Mezz	1.18	Missing Patch Tiles	0.06	0.3	0.018	0.018	m2		0.018
South East	West	Mezz	1.19	Missing Patch Tiles	0.3	0.02	0.006	0.006	m2		0.006
<b>East Column</b>											
				<b>Ground Floor</b>							
				<b>South</b>							
East	South	Ground	2.1	Missing Patch Tiles	0.55	0.6	0.330	0.330	m2		0.330
			2.1.1	Crack	0.2	0.05	0.100	0.100	m2		
				<b>West</b>							
East	West	Ground	2.2	Missing Isolated Tiles				25	nr	25	
East	West	Ground	2.3	Missing Patch Tiles	5.25	0.5	2.625	2.625	m2		2.625
				<b>North Elevation</b>							
East	North	Ground	2.4	Missing Isolated Tiles				20	nr	20	
East	North	Ground	2.5	Missing Patch Tiles	0.6	0.55	0.330	0.330	m2		0.330
				<b>East Elevation</b>							
East	East	Ground	2.6	Missing Isolated Tiles				20	nr	20	
East	East	Ground	2.7	Missing Patch Tiles	5.25	0.5	2.625	2.625	m2		2.625
East	East	Ground	2.7.1	Crack	2	0.05	0.100	0	m2		
East	East	Ground	2.7.2	Crack	1.1	0.05	0.055	0	m2		
				<b>1st Floor</b>							
				<b>North Elevation</b>							
East	North	Mezz	2.8	Missing Isolated Tiles				20	nr	20	
				<b>East Elevation</b>							
East	East	Mezz	2.9	Missing Isolated Tiles				20	nr	20	
				<b>South Elevation</b>							
East	South	Mezz	2.10	Missing Isolated Tiles				20	nr	20	
				<b>West Elevation</b>							
East	West	Mezz	2.11	Missing Isolated Tiles				20	nr	20	
<b>North East Column</b>											
				<b>Ground Floor</b>							
				<b>East Elevation</b>							

Project: Centre Point  
 Client: Multiplex  
 Title: Mosaic Tiles

Date:  
 Job No. 15027  
 App :



Column	Elevation	Floor	Item	Description Of Repair	Approx. Length (mm)	Approx. Height (mm)	M2 / M3	Qty	Unit	Isolated (nr)	Patches (m2)
North East	West	Ground	3.2	Missing Patch Tiles	0.15	0.45		1.0	m2		1.000
				<b>North Elevation</b>							
North East	North	Ground	3.3	Missing Isolated Tiles				20	nr	20	
North East	North	Ground	3.4	Missing Patch Tiles				0.5	m2		0.500
				<b>South Elevation</b>							
North East	South	Ground	3.5	Missing Isolated Tiles				8	nr	8	
North East	South	Ground	3.6	Missing Patch Tiles	0.6	0.55	0.330	0.330	m2		0.330
North East	South	Ground	3.7	Missing Patch Tiles	0.18	0.07	0.013	0.013	m2		0.013
North East	South	Ground	3.8	Missing Patch Tiles	0.1	0.1	0.010	0.010	m2		0.010
North East	South	Ground	3.9	Missing Patch Tiles	0.22	0.03	0.007	0.007	m2		0.007
				<b>West Elevation</b>							
North East	East	Ground	3.10	Missing Isolated Tiles				20	nr	20	
North East	East	Ground	3.11	Missing Patch Tiles				1.0	m2		1.000
				<b>1st Floor</b>							
				<b>North Elevation</b>							
North East	North	Mezz	3.12	Missing Isolated Tiles				20	nr	20	
North East	North	Mezz	3.13	Missing Patch Tiles				0.2	m2		0.200
				<b>East Elevation</b>							
				<b>South Elevation</b>							
North East	South	Mezz	3.16	Missing Isolated Tiles				20	nr	20	
North East	South	Mezz	3.17	Missing Patch Tiles				0.2	m2		0.2
				<b>West Elevation</b>							
North East	East	Mezz	3.18	Missing Isolated Tiles				20	nr	20	
North East	East	Mezz	3.19	Missing Patch Tiles				0.2	m2		0.200
				<b>North West Column</b>							
				<b>Ground Floor</b>							
				<b>South Elevation</b>							
North West	South	Ground	4.1	Missing Isolated Tiles				11	nr	11	
North West	South	Ground	4.2	Missing Patch Tiles	0.15	0.05	0.008	0.008	m2		0.008
North West	South	Ground	4.3	Missing Patch Tiles	0.1	0.05	0.005	0.005	m2		0.005
North West	South	Ground	4.4	Missing Patch Tiles	0.03	0.05	0.002	0.002	m2		0.002
North West	South	Ground	4.5	Missing Patch Tiles	0.22	0.05	0.011	0.011	m2		0.011
North West	South	Ground	4.6	Missing Patch Tiles	0.1	0.05	0.005	0.005	m2		0.005
North West	South	Ground	4.7	Missing Patch Tiles	0.6	0.3	0.180	0.180	m2		0.180
				<b>West Elevation</b>							
North West	West	Ground	4.8	Missing Isolated Tiles				20	nr	20	
North West	West	Ground	4.8.1	Previous bad repairs				20	nr	20	
North West	West	Ground	4.8.2	Crack				40	nr		
North West	West	Ground	4.8.3	Previous Bad repairs				20	nr		
North West	West	Ground	4.9	Missing Patch Tiles				1.0	m2		1.000
				<b>North Elevation</b>							
North West	North	Ground	4.10	Missing Isolated Tiles				20	nr	20	
North West	North	Ground	4.11	Missing Patch Tiles				0.2	m2		0.200
				<b>East Elevation</b>							
North West	East	Ground	4.12	Missing Isolated Tiles				12	nr	12	
North West	East	Ground	4.13	Missing Patch Tiles	0.2	0.3	0.060	0.060	m2		0.060
				<b>1st Floor</b>							
				<b>North Elevation</b>							
North West	North	Mezz	4.14	Missing Isolated Tiles				20	nr	20	
North West	North	Mezz	4.15	Missing Patch Tiles				0.2	m2		0.200
				<b>East Elevation</b>							
North West	East	Mezz	4.16	Missing Isolated Tiles				20	nr	20	
North West	East	Mezz	4.17	Missing Patch Tiles				1.0	m2		1.000
				<b>South Elevation</b>							
North West	South	Mezz	4.18	Missing Isolated Tiles				20	nr	20	
North West	South	Mezz	4.19	Missing Patch Tiles				0.2	m2		0.200
				<b>West Elevation</b>							
North West	West	Mezz	4.20	Chipped tiles				20	nr	20	



PAYE

Mosaic Tiles				App :			DATE				
Column	Elevation	Floor	Item	Description Of Repair	Approx. Length (mm)	Approx. Height (mm)	M2 / M3	Qty	Unit	Isolated (nr)	Patches (m2)
North West	West	Mezz	4.21	Crack				1.0	m2		1.000
	West Column										
				Ground Floor							
				North Elevation							
West	North	Ground	5.1	Missing Isolated Tiles				2	nr	2	
West	North	Ground	5.2	Missing Patch Tiles	1.37	0.08	0.110	0.110	m2		0.110
West	North	Ground	5.3	Missing Patch Tiles	0.6	0.5	0.300	0.300	m2		0.300
West	North	Ground	5.3.1	Crack				40.000	nr		
West	North	Ground	5.4	Missing Patch Tiles	0.4	0.1	0.040	0.040	m2		0.040
				East Elevation							
West	East	Ground	5.5	Missing Patch Tiles	1.25	0.06	0.075	0.075	m2		0.075
West	East	Ground	5.6	Missing Patch Tiles	0.2	0.06	0.012	0.012	m2		0.012
West	East	Ground	5.7	Missing Patch Tiles	0.05	0.2	0.010	0.010	m2		0.010
West	East	Ground	5.8	Missing Patch Tiles	0.05	0.05	0.003	0.003	m2		0.003
West	East	Ground	5.9	Missing Patch Tiles	0.05	0.07	0.004	0.004	m2		0.004
West	East	Ground	5.10	Missing Patch Tiles	5.25	0.5	2.625	2.625	m2		2.625
				South Elevation							
West	South	Ground	5.11	Missing Isolated Tiles				15	nr	15	
West	South	Ground	5.12	Missing Patch Tiles	0.6	0.5	0.300	0.300	m2		0.300
West	South	Ground	5.13	Missing Patch Tiles	0.44	0.05	0.022	0.022	m2		0.022
West	South	Ground	5.14	Missing Patch Tiles	0.3	0.05	0.015	0.015	m2		0.015
				West Elevation							
West	West	Ground	5.15	Missing Isolated Tiles				5	nr	5	
West	West	Ground	5.15.1	Crack	1.4	0.05	0.700	0.700	m2		
West	West	Ground	5.15.2	Crack	1	0.05	0.050	0.050	m2		
West	West	Ground	5.15.3	Crack	1.3	0.05	0.065	0.065	m2		
West	West	Ground	5.15.4	Remove and replace previous bad repair	0.3	0.05	0.015	0.015	m2		
West	West	Ground	5.15.5	Remove and replace previous bad repair	0.8	0.05	0.040	0.040	m2		
West	West	Ground	5.16	Missing Patch Tiles	5.25	0.5	2.625	2.625	m2		2.625
				1st Floor							
				South Elevation							
West	South	Mezz	5.17	Missing Isolated Tiles				20	nr	20	
West	South	Mezz	5.18	Missing Patch Tiles				0.1	m2		0.100
				North Elevation							
West	North	Mezz	5.19	Missing Isolated Tiles				20	nr	20	
West	North	Mezz	5.20	Missing Patch Tiles				0.1	m2		0.100
				East Elevation							
West	East	Mezz	5.21	Missing Isolated Tiles				20	nr	20	
West	East	Mezz	5.22	Missing Patch Tiles				0.2	m2		0.200
				West Elevation							
West	West	Mezz	5.23	Missing Isolated Tiles				20	nr	20	
West	West	Mezz	5.24	Missing Patch Tiles				0.2	m2		0.200
South West Column											
				Ground Floor							
				North Elevation							
South West	North	Ground	6.2	Missing Patch Tiles	0.6	0.5	0.300	0.300	m2		0.300
South West	North	Ground	6.3	Missing Patch Tiles	0.2	0.7	0.140	0.140	m2		0.140
South West	North	Ground	6.3.1	Replace damaged tiles (all glaze removed)	1.6	0.76	1.216	1.216	m2		
				East Elevation							
South West	East	Ground	6.4	Missing Isolated Tiles				13	nr	13	
South West	East	Ground	6.5	Missing Patch Tiles	2.5	0.5	1.250	1.250	m2		1.250
				South Elevation							

Project: Centre Point  
 Client: Multiplex  
 Title: Mosaic Tiles

Date:  
 Job No. 15027  
 App :



Column	Elevation	Floor	Item	Description Of Repair	Approx. Length (mm)	Approx. Height (mm)	M2 / M3	Qty	Unit	Isolated (nr)	Patches (m2)
South West	South	Ground	6.6	Missing Isolated Tiles				20	nr	20	
South West	South	Ground	6.7	Missing Patch Tiles				0.2	m2		0.200
				West Elevation							
South West	West	Ground	6.8	Missing Isolated Tiles				13	nr	13	
South West	West	Ground	6.8.1	Replace damaged tiles	0.5	0.1	0.050	0.050	m2		
South West	West	Ground	6.9	Missing Patch Tiles	2.5	0.5	1.250	1.250	m2		1.250
				1st Floor							
				South Elevation							
South West	South	Mezz	6.10	Missing Isolated Tiles				20	nr	20	
South West	South	Mezz	6.11	Missing Patch Tiles				0.1	m2		0.100
				North Elevation							
South West	North	Mezz	6.12	Missing Isolated Tiles				20	nr	20	
South West	North	Mezz	6.13	Missing Patch Tiles				0.1	m2		0.100
				East Elevation							
South West	East	Mezz	6.14	Missing Isolated Tiles				20	nr	20	
South West	East	Mezz	6.15	Missing Patch Tiles				0.2	m2		0.200
				West Elevation							
South West	West	Mezz	6.16	Missing Isolated Tiles				20	nr	20	
South West	West	Mezz	6.17	Missing Patch Tiles				0.2	m2		0.200
				West Internal							
				Ground Floor							
				South Elevation							
West Internal	South	Ground	7.1	Missing Isolated Tiles				4	nr	4	
West Internal	South	Ground	7.2	Missing Patch Tiles	0.6	0.5	0.300	0.300	m2		0.300
				West Elevation							
West Internal	West	Ground	7.3	Missing Isolated Tiles				3	nr	3	
West Internal	West	Ground	7.4	Missing Patch Tiles	5.25	0.5	2.625	2.625	m2		2.625
				East Elevation							
West Internal	East	Ground	7.5	Missing Isolated Tiles				3	nr	3	
West Internal	East	Ground	7.6	Missing Patch Tiles	5.25	0.5	2.625	2.625	m2		2.625
				North Elevation							
West Internal	North	Ground	7.7	Missing Patch Tiles	0.6	0.5	0.300	0.300	m2		0.300
				1st Floor							
				South Elevation							
West Internal	South	Mezz	7.8	Missing Isolated Tiles				5	nr	5	
West Internal	South	Mezz	7.9	Missing Patch Tiles	0.85	0.85	0.723	0.723	m2		0.723
				West Elevation							
West Internal	West	Mezz	7.10	Missing Isolated Tiles				5	nr	5	
West Internal	West	Mezz	7.11	Missing Patch Tiles	3.66	0.85	3.111	3.111	m2		3.111
				East Elevation							
West Internal	East	Mezz	7.12	Missing Patch Tiles	3.66	0.85	3.111	3.111	m2		3.111
				North Elevation							
West Internal	North	Mezz	7.13	Missing Isolated Tiles				5	nr	5	
West Internal	North	Mezz	7.14	Missing Patch Tiles	0.85	0.85	0.723	0.723	m2		0.723
				East Internal							
				Ground Floor							
				South Elevation							
East Internal	South	Ground	8.1	Missing Isolated Tiles				4	nr	4	
East Internal	South	Ground	8.2	Missing Patch Tiles	0.6	0.5	0.300	0.300	m2		0.300
				West Elevation							
East Internal	West	Ground	8.3	Missing Isolated Tiles				3	nr	3	
East Internal	West	Ground	8.4	Missing Patch Tiles	5.25	0.5	2.625	2.625	m2		2.625
				East Elevation							
East Internal	East	Ground	8.5	Missing Isolated Tiles				3	nr	3	
East Internal	East	Ground	8.6	Missing Patch Tiles	5.25	0.5	2.625	2.625	m2		2.625

Project: Centre Point  
 Client: Multiplex  
 Title: Mosaic Tiles

Date:  
 Job No. 15027  
 App :



Column	Elevation	Floor	Item	Description Of Repair	Approx. Length (mm)	Approx. Height (mm)	M2 / M3	Qty	Unit	Isolated (nr)	Patches (m2)
				<b>North Elevation</b>							
East Internal	North	Ground	8.7	Missing Patch Tiles	0.6	0.5	0.300	0.300	m2		0.300
				<b>1st Floor</b>							
				<b>South Elevation</b>							
East Internal	South	Mezz	8.9	Missing Patch Tiles	0.85	0.85	0.723	0.723	m2		0.723
				<b>West Elevation</b>							
East Internal	West	Mezz	8.10	Missing Isolated Tiles				5	nr	5	
East Internal	West	Mezz	8.11	Missing Patch Tiles	3.66	0.85	3.111	3.111	m2		3.111
				<b>East Elevation</b>							
East Internal	East	Mezz	8.12	Missing Isolated Tiles				5	nr	5	
East Internal	East	Mezz	8.13	Missing Patch Tiles	3.66	0.85	3.111	3.111	m2		3.111
				<b>North Elevation</b>							
East Internal	North	Mezz	8.14	Missing Isolated Tiles				5	nr	5	
East Internal	North	Mezz	8.15	Missing Patch Tiles	0.85	0.85	0.723	0.723	m2		0.723
				<b>13</b>							
				<b>Ground Floor</b>							
				<b>East Elevation</b>							
J3	East	Ground	9.1	Missing Isolated Tiles				250	nr	250	
J3	East	Ground	9.1.1	Damaged tiles				20	nr		
J3	East	Ground	9.1.2	Crack	Crack	1.5	0.05	0.075	0.075	m2	
				Damaged by others Missing Patch Tiles	0.37	1.05	0.389	0.389	m2		0.389
J3	East	Ground	9.3	Missing Patch Tiles	0.1	0.1	0.010	0.010	m2		0.010
				<b>North Elevation</b>							
J3	North	Ground	9.4	Damage by others Missing Patch Tiles							
J3	North	Ground	9.4.1	Crack	Crack	1.5	0.05	0.075	0.075	m2	
				<b>South Elevation</b>							
J3	South	Ground	9.5	Missing Isolated Tiles				25	nr	25	
				<b>West Elevation</b>							
J3	West	Ground	9.6	Missing Isolated Tiles				25	nr	25	
J3	West	Ground	9.7	Missing Patch Tiles	1	0.1	0.100	0.100	m2		0.100
J3	West	Ground	9.7.1	replace metal with tiles				20.000	nr	20	
J3	West	Ground	9.7.2	Crack	1.5	0.05	0.075	0.075	m2		
J3	West	Ground	9.7.3	Crack	1.5	0.05	0.075	0.075	m2		
				<b>1st Floor</b>							
				<b>North Elevation</b>							
J3	North	Mezz	9.8	Missing Isolated Tiles				4	nr	4	
				<b>South Elevation</b>							
J3	South	Mezz	9.9	Missing Isolated Tiles				20	nr	20	
J3	South	Mezz	9.9.1	Missing Isolated Tiles							
				<b>West Elevation</b>							
J3	West	Mezz	9.10	Missing Isolated Tiles				10	nr	10	
				<b>14</b>							
				<b>Ground Floor</b>							
				<b>West Elevation</b>							
J4	West	Ground	10.1	Missing Isolated Tiles				15	nr	15	
J4	West	Ground	10.1.1	Missing Isolated Tiles				20	nr	20	
				<b>North Elevation</b>							
J4	North	Ground	10.2	Missing Isolated Tiles				8	nr	8	
J4	North	Ground	10.3	Missing Patch Tiles	0.2	0.05	0.010	0.010	m2		0.010
J4	North	Ground	10.4	Missing Patch Tiles	0.6	0.2	0.120	0.120	m2		0.120
				<b>South Elevation</b>							
J4	South	Ground	10.5	Missing Isolated Tiles				9	nr	9	
				<b>East Elevation</b>							
J4	East	Ground	10.6	Missing Isolated Tiles				15	nr	15	
J4	East	Ground	10.7	Missing Patch Tiles	0.1	0.1	0.010	0.010	m2		0.010



PAYE

[illegible]

<b>Project:</b>	Centre Point	<b>Date:</b>	
<b>Client:</b>	Multiplex	<b>Job No.</b>	15027
<b>Title:</b>	Mosaic Tiles	<b>App :</b>	



PAYE

[illegible]