

EXISTING EXTERNAL WINDOW AND DOORS TO BE REMOVED




Notes

All dimensions to be verified on site. Do not scale this drawing. All discrepancies to be clarified with project Architect.


This drawing is the property of Benoy Architects and is issued on the condition it is not reproduced, retained or disclosed to any unauthorised person, either wholly or in part without written consent of Benoy Ltd.

Ordnance Survey material is used with the permission of The Controller of HMSO. Crown copyright AR 159670.

The CDM hazard management procedures for the Benoy aspects of the design of this project are to be found on the "Benoy - Designer's Hazard Identification and Management Sheet" and/or drawings. The full project design team's comprehensive set of hazard management procedures are available from the Planning Supervisor/Safety Coordinator appointed for the project.

- KEY**
-  WINDOWS, WALL OR DOORS TO BE REMOVED (DEMOLISH)
 -  WINDOWS TO BE REPAIRED/ REPLACED TO MATCH EXISTING
 -  LEADED LIGHTS RETAINED WITH SECONDARY GLAZING TO BE ADDED

B00	13/04/17	Issued for Planning	OG	RP
A00	10/02/17	First issue	PL	RP
Rev	Date	Description	By	Chk'd



Client
EMBASSY OF THE PEOPLE'S REPUBLIC OF CHINA

Project
CHINESE EMBASSY CULTURAL OFFICE REFURBISHMENT / EXTENSION

Drawing Title
DEMOLITION ELEVATION MUSE BUILDING EAST

Drawn By PL	Checked By RP
-----------------------	-------------------------

Scale 1:50@A3	Date JAN 2017
-------------------------	-------------------------

Project No. 5927	Drawing No. BNY-MU-05-E001	Revision B00
----------------------------	--------------------------------------	------------------------

Status
PLANNING

t +44 (0) 207 404 7666
f +44 (0) 207 404 7980
a london@benoy.com

www.benoy.com