




Notes

All dimensions to be verified on site. Do not scale this drawing. All discrepancies to be clarified with project Architect.

This drawing is the property of Benoy Architects and is issued on the condition it is not reproduced, retained or disclosed to any unauthorised person, either wholly or in part without written consent of Benoy Ltd.


Ordnance Survey material is used with the permission of The Controller of HMSO. Crown copyright AR 159670.

The CDM hazard management procedures for the Benoy aspects of the design of this project are to be found on the "Benoy - Designer's Hazard Identification and Management Sheet" and/or drawings. The full project design team's comprehensive set of hazard management procedures are available from the Planning Supervisor/Safety Coordinator appointed for the project.

- KEY**
-  WINDOWS, WALL OR DOORS TO BE REMOVED (DEMOLISH)
 -  WINDOWS, WALL OR DOORS TO BE REPAIRED/ REPLACED TO MATCH EXISTING
 -  LEADED LIGHTS RETAINED WITH SECONDARY GLAZING TO BE ADDED



B00	13/04/17	Issued for Planning	OG	RP
A01	10/02/17	Stage 3 issue	PL	RP
A00	27/01/17	First issue	OG	RP
Rev	Date	Description	By	Chk'd



Client
**EMBASSY OF THE PEOPLE'S
 REPUBLIC OF CHINA**

Project
**CHINESE EMBASSY
 CULTURAL OFFICE
 REFURBISHMENT / EXTENSION**

Drawing Title
**DEMOLITION ELEVATION
 MAIN BUILDING
 SOUTH**

Drawn By
PL

Checked By
RP

Scale
1:100@A3

Date
JAN 2017

Project No. | Drawing No. | Revision
5927 | BNY-MA-05-S001 | B00

Status
PLANNING

t +44 (0) 207 404 7666
 f +44 (0) 207 404 7980
 e london@benoy.com

www.benoy.com

South Elevation

Datum=106.00m

Datum=106.00m