

Holes to be carefully repaired using mortar colour to match that of the existing mortar.

PROPOSED FIFTH FLOOR INTERNAL WALL DETAIL architecture & interior design Unit 1 9a Dallington Street Clerkenwell

London EC1V OBQ