


Appendix

BREEAM Ecology Report

KOKO



Western façade of the building



Area of ruderal plants



Service pipes with pigeon deterrents



Pigeons on the roof



Slate tiled roof in good condition



Flat asphalt roof in good condition