

Double glazed unit structurally bonded to aluminium carrier frame

Dashed line of existing corrugated roof - top of coping stone to line up with this line

Coping stone

Galvanised steel liner to gutter

Additional brick masonry built up to higher level where required

Rainwater downpipe

Existing brickwork wall cleaned, wire brushed and painted with masonry paint

Timber external door

Double glazed unit structurally bonded to aluminium carrier frame

Dashed line of existing corrugated roof - top of coping stone to line up with this line

Coping stone

Galvanised steel liner to gutter

Additional brick masonry built up to higher level where required

Joinery - Storage

Existing brickwork wall cleaned, wire brushed and painted with masonry paint

Timber external door in background